

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE American Tower Scanning REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35936	4. LICENSE NUMBER(S) 21-32347-01	5. DATE(S) OF INSPECTION 8/21/2007	
6. INSPECTION PROCEDURES USED 87113	7. INSPECTION FOCUS AREAS 3.1-3.7		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 3111	2. PRIORITY 5	3. LICENSEE CONTACT Mark Gledhill	4. TELEPHONE NUMBER 519-331-9684
-----------------------------------	-------------------------	---	--

Main Office Inspection Next Inspection Date: **08/2012**

Field Office 3560 Pine Grove Avenue

Temporary Job Site _____

PROGRAM SCOPE

The licensee's main office is located in Sarnia, Ontario; Canada. However, the licensee's US mailing address is located at an office complex in Port Huron, Michigan. The licensee is a tower scanning company that performed real time scanning on above ground reaction tanks for the purpose of inner structural analysis. The licensee's clients were mainly refineries and industrial chemical companies. The licensee possesses a number of sources but has only entered the United States three times on 2003 to conduct licensed operations. The licensee's main storage area is located in Canada with a staging area in Port Huron, Michigan. The licensee's staff consists of the RSO/President and one other technician.

Performance Observations

As of the inspection date, the licensee transported and performed licensed operations with a number of sources on three separate occasions in 2003. The inspector interviewed the RSO/President of the company and found that he was knowledgeable regarding NRC regulations. The inspector reviewed a representative sample of paperwork provided by the licensee which was stored in Canada; no abnormal issues were identified. Since the licensee does not stored licensed material within the United States, the inspector was unable to physical confirm issues concerning security. However, interviews with the RSO/President with the inspector indicated that a sufficient amount of knowledge and equipment is available to ensure the security of licensed material while within US jurisdiction.