

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

830 Power Building

March 1, 1978

Central File
50-390
391

Mr. J. P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 1217
230 Peachtree Street, NW.
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 78-02 - IE:RII:JPO
50-327, -328, -390, -391, -438, -439, -518, -519, -520, -521,
-553, -554 - SEQUOYAH, WATTS BAR, BELLEFONTE, HARTSVILLE, AND
PHIPPS BEND NUCLEAR PLANTS

In response to your January 30, 1978, letter which transmitted
IE Bulletin 78-02, we are submitting the following results of our
investigations for Sequoyah, Watts Bar, Bellefonte, Hartsville,
and Phipps Bend Nuclear Plants.

A review of the affected nuclear plants revealed that TVA neither
uses, nor do we plan to use, unprotected terminal blocks in systems
which must function in the post-accident environment.

Very truly yours,

J. E. Gilleland
you J. E. Gilleland
Assistant Manager of Power

cc: Mr. E. G. Case, Acting Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Office of Inspection and Enforcement
Division of Reactor Operations Inspection
U.S. Nuclear Regulatory Commission
Washington, DC 20555

AO 2
GP