

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1 LICENSEE/LOCATION INSPECTED: US Inspection Services 705 Albany Street Dayton, OH 45408 REPORT 2007001	2 NRC/REGIONAL OFFICE US Nuclear Regulatory Comm Reg III 2447 Warwick Rd Springfield Ohio 45502
---	--

3 DOCKET NUMBER(S) 03035059	4 LICENSEE NUMBER(S) 34-06943-02	5 DATE(S) OF INSPECTION 10/25/07
--------------------------------	-------------------------------------	-------------------------------------

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Parker		10/25/07

**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**



1. LICENSEE <b>U. S. Inspection Services</b> REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE <b>Region III</b>	
3. DOCKET NUMBER(S) 030-35059	4. LICENSE NUMBER(S) 34-06943-02	5. DATE(S) OF INSPECTION October 25, 2007	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Chris Dixon	4. TELEPHONE NUMBER 937/228-9729
-----------------------------	------------------	------------------------------------	-------------------------------------

Main Office Inspection      Next Inspection Date: 10/08

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a radiographer located in Dayton, Ohio with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has twelve full time radiographers and radiographer assistants and is in possession of ten 660B and 880 exposure devices. Licensee is in the process of merging with ACCUREN. Upon completion of the merger they will be the northern division of ACCUREN.

**Performance Observations**

Licensee is located in an Agreement state and as such the inspection was of limited scope. No temporary job site was observed as the closest was three hours away. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 1000 mRem/yr on average.

No violations of requirements were noted.