

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Weatherford International, Inc.
& Subsidiaries & Affiliate Companies
500 Winscott Road
Forth Worth, Texas 76126

2. NRC/REGIONAL OFFICE

USNRC Region IV
611 Ryan Plaza Drive
Arlington, Texas 76011-4005

RECEIVED

NOV 14 2007

REPORT NUMBER(S) 2007-001

DNMS

3. DOCKET NUMBER(S)

030-30118

4. LICENSEE NUMBER(S)

42-26891-01

5. DATE(S) OF INSPECTION

6/28, 9/10, 9/12, and 10/15/2007

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- ☐ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- ☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

- A. 10 CFR 39.37 requires, in part, that each licensee conduct a semi-annual physical inventory to account for all licensed material received and possessed under the license.



Contrary to the above, the licensee's field office in Casper, Wyoming performed semi-annual physical inventories that did not account for all licensed material received and possessed under the license. Specifically, the inventories did not include neutron generators which contain approximately 3 curies of tritium, licensed material that was received and possessed under the license.

- B. 10 CFR 39.31(a)(2), requires in part, that the licensee may not use a container to store licensed material unless the container has securely attached to it a durable, legible, and clearly visible label. The label must contain the radiation symbol and other wording as specified.

Contrary, to the above, on the day of the inspection of the field office in Casper, Wyoming, the licensee had five neutron generators which contained approximately 3 curies of tritium a piece of licensed material stored in containers that did not have the required labeling.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Christopher Sean Perry		2-NOV-2007
NRC INSPECTOR	Anthony D. Gaines		10/30/07