

70-057-020  
80-034-080

*Mills*

TENNESSEE VALLEY AUTHORITY

400 Chestnut Street Tower II

13 JUL 14 1980  
July 11, 1980

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - REMOVAL OF DOCUMENTATION TAGS  
AND CONDUIT SUPPORT CLAMPS - NCR 2381R - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE  
Inspector M. Thomas on June 9, 1980, in accordance with 10 CFR 50.55(e).  
Enclosed is our first interim report. We expect to submit our  
next report by August 29, 1980.

If you have any questions concerning this matter, please get in touch  
with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*L. M. Mills*  
L. M. Mills, Manager  
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure)  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

B019  
S  
~~100~~  
1/1

8008210369

S

OFFICIAL COPY

Enclosure  
WATTS BAR NUCLEAR PLANT UNITS 1 AND 2  
Removal of Documentation Tags and Conduit Support Clamps  
10 CFR 50.55(e)  
NCR No. 2381R  
FIRST INTERIM REPORT

Description of Deficiency

The identification tags and conduit support clamps for safety system power supplies were removed without documentation as required by procedure WBNP-QCP-33. Support tag CS-AB-15,589 is missing and conduit support tag CS-AB-15,590 has been attached to the wrong support.

Interim Progress

TVA is currently investigating this problem and we expect to supply additional information to the NRC by August 29, 1980.