

50-328
Willa

TENNESSEE VALLEY AUTHORITY

USNRC REGION II
CHATTANOOGA, TENNESSEE 37401
ATLANTA, GEORGIA 30303
400 Chestnut Street Tower II

July 04, 1980 3:28
JUL 20 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNIT 2 AND WATTS BAR NUCLEAR PLANT UNITS
1 AND 2 - DEFECTIVE REACTOR VESSEL UPPER INTERNALS GUIDE TUBE
SUPPORT PINS - NCR SQN NEB 8006 AND NCR WBN NEB 8001 -
SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. J. Gouge on March 24, 1980, in accordance with 10 CFR 50.55(e).
An interim report was submitted on April 23, 1980. We expect to submit
our next report by September 11, 1980.

Westinghouse has not completed the evaluation of the guide tube pins
taken from an operating plant. TVA and Westinghouse are proceeding
with plans to replace the pins at Sequoyah unit 2 and Watts Bar units
1 and 2 so as not to impact the current construction schedule. If,
however, the evaluation is finished before the pins are replaced and
if the evaluation determines that pin replacement is not necessary,
then the pins may not be replaced.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

13019
5/10
OFFICIAL COPY