

ENCLOSURE

CONTROL LOOP BISTABLES FAIL TO UNDESIRABLE
POSITION OF LOSS OF CONTROL POWER
NCR MEB 79-9
FIRST INTERIM REPORT

Description of Deficiency

Bistables associated with certain control loops in the Auxiliary Control Room have been found to fail in an undesirable position on loss of control power. This was due to an error in the wiring of the instrumentation. The problem does not exist in the Main Control Room instrumentation.

Interim Progress

The problem has been identified and the Electrical Engineering Branch and the Sequoyah-Watts Bar Project are jointly reviewing the Auxiliary Control Room instrumentation for other instances of this problem.

7903270527