

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
500C Chestnut Street Tower II

MAY 17 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - TENSILE ANCHOR CAPACITIES
LOWER THAN DESIGN ALLOWABLES - NCR CEB 79-6 - SECOND INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Tom Burdette on February 12, 1979, in accordance with 10 CFR 50.55(e).
Our first interim report was submitted on March 14, 1979.

Testing of the stud anchors is still in progress, and we expect now
to submit our next report by August 6, 1979.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

J. E. Gilleland
Assistant Manager of Power

cc: Mr. John G. Davis, Acting Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
~~Boat~~
S 1/0

7905230 3 81