

TELEPHONE REPORT

*Handwritten:* Hendy

**REGULATORY DOCKET FILE COPY**

FACILITY: Watts Bar Units 1 and 2

DOCKET #: 50-390, 391

DATE: 8/6/79

TIME: 2:00 pm

LIC. OCC. #: \_\_\_\_\_

SUBJECT: Defective Steel in Main Steam Pipe Restraints

NCR # WB-C-79-05

DESCRIPTION OF OCCURRENCE: The licensee reported that a construction QA

audit identified that a possible defective steel was used in the

fabrication of the main steam valve room pipe restraints. TVA

is evaluating. TVA will confirm on 8/16/79. Written report

due 9/5/79.

M. Thomas

SIGNATURE

7908150556

*Handwritten:* 3019  
~~4002~~  
5/10  
790275