

664
765
2308

APR 11 1958

The Martin Co.
Baltimore 3, Maryland

Attention: Mr. Paul Guinn

Gentlemen:

This refers to the inspection conducted on October 22, 1957 of your activities authorized under Source Material License Nos. D-3572 with Amend. #1 and 2; C-3117 with Amend. #1; and C-3508 with Amend. #1, 2, 3, and 4; and Byproduct Material License Nos. 19-1398-1, 2, 3, 5, 6, 7, 8, and 9.

It appears that certain of your activities were not conducted in full compliance with the conditions of your Byproduct Material and Source Material Licenses and the requirements of the AEC's regulations in Parts 20 and 30, Title 10, Code of Federal Regulations in that:

1. The carton containing the 6.6 pounds of UO_2 was not labeled with the proper radiation signs as required by Section 20.203(f).
2. The 1 mc Thulium 170 source was not covered by a specific license as required in Section 30.3 of 10 CFR 30.
3. Leak tests of the Strontium 90 sealed sources were not carried out as required by Condition 14 of License No. 19-1398-2.

It is noted that these deficiencies were called to your attention and you agreed to take the necessary corrective action and verified in your letter of February 28, 1958 the action which would be taken. Particular attention will be given these items during the next inspection of your activities.

There were no other items of noncompliance reported to us as a result of this visit. We appreciate the cooperation given to the AEC representative.

Very truly yours,

James R. Mason, Chief
Isotopes Branch
Division of Licensing and Regulation

A/29