

From: <charles.m.molnar@us.westinghouse.com>
To: <bjb@nrc.gov>, <ecm@nrc.gov>, <sda@nrc.gov>, <sxd@nrc.gov>, <mas4@nrc.gov>, <ixa@nrc.gov>
Date: 9/5/03 2:00PM
Subject: TB-03-00, CROSSFLOW Ultrasonic Flow MeasurmentSystem Signal Issues

bjb@nrc.gov
ecm@nrc.gov
sda@nrc.gov
sxd@nrc.gov
mas4@nrc.gov
ixa@nrc.gov

Rhonda O. Doney/CENO/USNUS/BNFL-TEMP@ABB_USSEV_IMS
Hank A. Sepp/North-America/Westinghouse@Exchange
Bill Klein/North-America/Westinghouse@Exchange
Charles B. Brinkman/CENSYS/USNUS/BNFL-TEMP@ABB_USSEV_IMS
alopez@amag-inc.com

Subject: TB-03-00, CROSSFLOW Ultrasonic Flow MeasurmentSystem Signal Issues

Security Level:? Internal

Per our prior discussions, attached for your information and use is a copy of Westinghouse Electric Company LLC, Technical Bulletin, TB-03-6, "CROSSFLOW Ultrasonic Flow MeasurmentSystem Signal Issues".

(See attached file: TB-03-6.PDF)

Chuck Molnar
Westinghouse Electric Company LLC
Regulatory Compliance & Plant Licensing
(860) 731-6286

CC: <rhonda.o.doney@us.westinghouse.com>,
<Hank_A._Sepp/North-America/Westinghouse%Exchange@us.westinghouse.com>,
<Bill_Klein/North-America/Westinghouse%Exchange@us.westinghouse.com>,
<charles.b.brinkman@us.westinghouse.com>, <alopez@amag-inc.com>

B-35