NRC FORM 591M PAR	T 1		U.S. NUCLEAR REGULATORY COMMISSION					
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION								
1 LICENSEE/LOCATION	NSPECTED:		2. NRC/REGIONAL OFFICE					
Mid American Insp Service			US Nuclear Regulatory Comm					
P.O. BOX 1427			2443 Warnnille Rd					
Caylord, MI 49735			Suite 310					
REPORT 2008-10 1/002			Lisle, II 60532					
3 DOCKET NUMBER(S)	7,002	4. LICENSEE NUMBER(S)		5. DATE(S)	OF INSPECTION			
030-31160	,	21-26060-0	. 1	Jan 17,20		1		
LICENSEE:					·			
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspection. The inspection findings are as follows: 1. Based on the inspection findings, no violations were identified. 2. Previous violation(s) closed. 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied. Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s): 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)								
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested. Title Printed Name Signature Date								
LICENSEE'S REPRESENTATIVE			,		}	1		
			1	,, 				

NRC FORM 591M PAR (10-2003) 10 CFR 2 201	Т3	U.S. Docket File Information SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION		S. NUCLEAR REGULATORY COMMISSION					
1. LICENSEE 2. NRC/REGIONAL OFFICE									
Mid American	Inspection								
REPORT NUMBER(S) 2008-007			Region III						
3. DOCKET NUMBER(S)		4. LICENSE NUMBER(S)		5. DATE(S) OF INSPECTION					
030-31160		21-26060-01		January 17, 2008					
6. INSPECTION PROCEDURES USED		7. INSPECTION FOCUS AREAS							
87126		03.01 - 03.07							
SUPPLEMENTAL INSPECTION INFORMATION									
1. PROGRAM CODE(S) 2. PRIORITY		3. LICENSEE CONTACT		4. TELEPHONE NUMBER					
03320	1	Terry Wilkins	· · · · · · · · · · · · · · · · · · ·	989/732-8059					
X Main Office In:	spection	Next Inspection Date: 1/09		1/09					
Field Office									
Temporary Job Site									
		PROGRA	M SCOPE						
The licensee is a radiographer located in Gaylord, Michigan with authorization to use material at temporary job sites. This licensee has four full time radiographers and owns six 660B exposure devices. This inspection also included a review of licensee's implementation of the IC Order.									
Performance Observations									
At the time of the inspection, licensee was performing radiography at the Canadian border. Therefore no temporary job site was observed.									
The inspector reviewed the paperwork associated with the use of the radiographic devices at the main office and interviewed personnel there that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.									
Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 1000 mrem on average									
A review of IC implementation indicated that there had been no changes since the last inspection. The previous violation for failure to have documentation of the response plan with local law enforcement was reviewed and found to be satisfactory.									
No violations of requirements were noted.									