

1/7/74

-2-

Date: 1/7/74

P/S 3

NotificationItem or EventRegional ActionIon

Island 1 & 2 Telephone-1/4
 50-289 &
 50-320)

The building spray pump motors are required to be returned to the manufacturer (W) for rework. The problem is as described in FS&EB Control Form -Action Code I/73-121.

Routine Follow-up.

al & Environmental Protection

stals, Inc. Inspection
 s. SNM-65 12/27-28
 and SMB-179

The licensee was casting depleted uranium and not performing beta gamma surveys. As a result, undetected contamination was present. (End window G.M. readings at contact: employees shoe bottoms, 5 mR/hr inspector shoe bottoms from single entry of work area 1 mR/hr, smear of work table 2 mR/hr, smear at bottom step leading to area 17,500 dpm/100 cm², smear at entrance to plant 100 dpm/100 cm²). There were no contamination control measures in effect. Management stated that they could not guarantee that employees were not wearing contaminated shoes home.

The president of the company was contacted by telephone 1/4 and told that immediate action to detect and prevent contamination spread must be instituted. The homes of appropriate employees are to be checked by the licensee. Management agreed to take immediate action. The plant will be revisited 1/8 to evaluate licensee action.

tection

1/7/74

-2-

Date: 1/7/74

NotificationItem or EventRegional ActionIon

Island 1 & 2 Telephone-1/4
 50-289 &
 50-320)

The building spray pump motors are required to be returned to the manufacturer (W) for rework. The problem is as described in FS&EB Control Form -Action Code I/73-121.

Routine Follow-up.

Health & Environmental Protection

Metals, Inc. Inspection
 Os. SNM-65 12/27-28
 and SMB-179

The licensee was casting depleted uranium and not performing beta gamma surveys. As a result, undetected contamination was present. (End window G.M. readings at contact: employees shoe bottoms, 5 mR/hr inspector shoe bottoms from single entry of work area 1 mR/hr, smear of work table 2 mR/hr, smear at bottom step leading to area 17,500 dpm/100 cm², smear at entrance to plant 100 dpm/100 cm²). There were no contamination control measures in effect. Management stated that they could not guarantee that employees were not wearing contaminated shoes home.

The president of the company was contacted by telephone 1/4 and told that immediate action to detect and prevent contamination spread must be instituted. The homes of appropriate employees are to be checked by the licensee. Management agreed to take immediate action. The plant will be revisited 1/8 to evaluate licensee action.

Protection