

Barry S. Allen
Vice President - Nuclear

419-321-7676
Fax: 419-321-7582

April 10, 2008
L-08-104

ATTN: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

SUBJECT:

Davis-Besse Nuclear Power Station, Unit 1
Docket No. 50-346, License No. NPF-3
Davis-Besse Nuclear Power Station Unit 1 Steam Generator Tube
Circumferential Cracking Report for the Fifteenth Refueling Outage

In accordance with License Condition 2.C(7) of the Davis-Besse Nuclear Power Station Unit 1 (DBNPS) Operating License, the FirstEnergy Nuclear Operating Company (FENOC) hereby provides required information regarding the January 2008 eddy current inspection of the DBNPS steam generator tubes performed during the Fifteenth Refueling Outage (15RFO).

The information specified by the license condition is provided below.

- a. No circumferential cracking was found inboard of any installed repair roll.
- b. There was one tube in Steam Generator (SG) 2A that had a new circumferential Primary Water Stress Corrosion Cracking (PWSCC) crack indication in the tube-to-tubesheet seal weld heat affected zone. This tube was plugged in accordance with Technical Specification 3.4.5.b requirements. The indication met the reporting requirements of License Condition 2.C(7). This indication was reported to the NRC by teleconference on January 12, 2008. No tubes in SG 1B had similar indications.
- c. The large-break loss-of-coolant accident (LBLOCA) Leakage Integrity Evaluation was performed and was included in the DBNPS 15RFO Steam Generator Condition Monitoring and Operational Assessment Evaluation. The projected best-estimate LBLOCA leakage for degradation observed during 15RFO is 0.0 gpm from SG 1B and 0.16 gpm from SG 2A.

ADD
NR

Davis-Besse Nuclear Power Station


L-08-104

Page 2

The estimated combined steam generator leak rate is less than the leak rate assumed in the LBLOCA accident analysis in the Davis-Besse Updated Safety Analysis Report. Accordingly, the off-site dose consequences from a LBLOCA would be below the 10 CFR Part 100 limits.

There are no regulatory commitments contained in this letter. If there are any questions or if additional information is required, please contact Mr. Thomas A. Lentz, Manager – Fleet Licensing, at (330) 761-6071.

Sincerely,

A handwritten signature in cursive script that reads "Gary S. Allen".

cc: NRC Region III Administrator
NRR Project Manager - Davis-Besse Nuclear Power Station
NRC Resident Inspector - Davis-Besse Nuclear Power Station
Executive Director, Ohio Emergency Management Agency,
State of Ohio (NRC Liaison)
Utility Radiological Safety Board