

Russell W. Goyette
7 Strathmere Street
Waretown, NJ 08758
March 27, 2008

Mr. Paol-Tsin Kuo
Director
NRC Division of License Renewal
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Re: Oyster Creek - Failure to Meet Safety Standards

Dear Mr. Kuo:

It is premature to conclude your review of Oyster Creek regarding the application to operate another twenty years. The operating track record of Exelon has been dismal and there is no indication that current management will be able to operate this decaying facility into the future.

Let me cite the following:

1. The Exelon management has been unable to maintain radiation monitors in the area of the plant.
2. There have been numerous planned and unplanned radiological "spills" into area waters. I possess a deformed crab taken from the discharge waters of Oyster Creek. I believe these deformities were caused by nuclear radiation. A thorough review would have examined this crab. No such examination ever took place. Any review was not very "thorough."
3. NRC guidelines call for a working warning system to inform area residents if a radiological release has taken place. I live about three miles south of the plant; I have never taken part in, or ever heard of, a test. The review is incomplete.
4. Each nuclear plant requires an evacuation plan. No workable plan exists for Oyster Creek. Even the New Jersey State Police is on record saying no workable evacuation plan exists for Oyster Creek.

Even the NRC's guidelines are not being followed. The review is incomplete. Approval is premature.


Kindly respond to the above.

Sincerely,

Russell W. Goyette
A114

GOVETTE
7 STRATHMERE ST.
WARETOWN, NJ 08758

TRENTON NJ 086
28 MAR 2008 PM 3 T



MR. PAOL-TSIN KUO
DIRECTOR
NRC DIVISION OF LICENSE RENEWAL
OFFICE OF NUCLEAR REACTOR REGULATION
U.S. NUCLEAR REGULATORY COMMISSION
WASHINGTON, DC 20515-5100

Janne