

## TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

June 17, 1981

Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Region II - Suite 3100  
101 Marietta Street  
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAULTY FILLET WELDS -  
NCR 2111R - SIXTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on February 20, 1980, in accordance with 10 CFR 50.55(e) in conjunction with similar deficiencies designated as NCR's 2806R, 2091R, 2101R, 2120R, 2128R, 2137R, and 2375R. Interim reports were submitted on March 19, May 6, August 8, and October 31, 1980, and February 6, 1981. TVA is still in the process of reinspecting and repairing fillet welds. We expect to provide additional information by October 14, 1981.

If you have any questions concerning this matter, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*L. M. Mills*  
for L. M. Mills, Manager  
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555

IR27  
5/10