

APPENDIX A  
NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar 1

Docket No. 50-390  
License No. CPPR-91

As a result of the inspection conducted on April 27-30, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion XVI, as implemented by Section 17.1A.16 of the Watts Bar FSAR requires that "Measures shall be established to assure that conditions adverse to quality, such as...are promptly identified and corrected." Corrective action described in TVA's response of January 25, 1982 to enforcement action on loose jam nuts observed on finalized hangers, 390/81-19-02, included reinspections of accepted hangers, oral and written instructions, training and procedural revisions.

Contrary to the above, on April 30, 1982, adequate measures had not been taken to assure that certain conditions adverse to quality were promptly identified and corrected in that two previously accepted safety related pipe hangers 62-1VC-R69 and 62-1CVC-R76 were found with loose jam nuts. Moreover, the licensee provided no objective documented evidence to verify that corrective actions implemented as a result of violation 390/81-19-02 produced the confidence level needed to assure that hanger installations finalized prior to the date of the above violation were now acceptable.

This is a Severity Level V Violation (Supplement II.E).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: JUN 04 1982