
## 400 Chestnut Street Tower II

September 23, 1981

WBRD-50-390/81-40 WBRD-50-391/81-39

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:



The subject deficiency was initially reported to NRC-OIE Inspector R. V. Crlenjak on April 10, 1981 in accordance with 10 CFR 50.55(e) as NCR CEB 8106. Interim reports were submitted on May 11 and August 18, 1981. We expect to provide additional information by December 2, 1981. TVA is continuing to reanalyze the piping problem with the correct valve modeling.

If you have any questions, please get in touch with D. L. Lambert at FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager Nuclear Regulation and Safety

cc: Mr. Victor Stallo, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 2:555

IE27