

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

October 13, 1981



Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:


WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAULTY FILLET WELDS - NCR 2111R - SEVENTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector R. W. Wright on February 20, 1980 in accordance with 10 CFR 50.55(a) in conjunction with similar deficiencies designated as NCR's 2806R, 2091R, 2101R, 2120R, 2128R, 2137R, and 2375R. Interim reports were submitted on March 19, May 6, August 8, and October 31, 1980, and February 6 and June 17, 1981. TVA is still in the process of reinspecting and repairing fillet welds. We expect to provide additional information by December 21, 1981.

If you have any questions concerning this matter, please get in touch with M. R. Wisenburg at FTS 857-2778.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


M. R. Wisenburg,
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
S
1/0

8110200362 811013
PDR ADDCK 05000390
8 PDR