

TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower

October 19, 1981

USNRC REGION II
ATLANTA, GEORGIA
OCT 21 4 9:20

WBRD-50-390/81-13
WBRD-50-391/81-12

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - FAILURE OF THE GENERATOR SYSTEM TO
SUPPLY ADEQUATE VOLTAGE TO THE SAFETY-RELATED BOARDS - WBRD-50-390/81-13,
WBRD-50-391/81-12 - FOURTH INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
M. Thomas on January 5, 1981 in accordance with 10 CFR 50.55(e) as
NCR WBN EEB 8009. Interim reports were submitted on February 4,
April 13, and July 7, 1981. We expect to submit our next report by
November 24, 1981.

TVA is still in the process of evaluating the alternative solutions as
delineated in our third interim report.

If you have any questions, please get in touch with R. H. Shell at
FTS 857-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

IE27
5
1/6

8110290266 811019
PDR ADOCK 05000390
S PDR