TENNESSEE VALLEY AUTHORITY USING REGION :

400 Chestnut Street Tower II

31 NOV 18 A8 . 04 November 16, 1981

AT ANTA, GEORGIA

HTRD-50-518/81-17, -519/81-13, -520/81-15, -521/81-13 PBRD-50-553/81-18, -554/81-12 WBRD-50-390/81-63, -391/81-59 BLRD-50-438/81-46. -439/81-49 YCRD-50-566/81-17,-567/81-14

Mr. James P. O'Reilly, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Region II - Suite 3100 101 Marietta Street Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE, PHIPPS BEND, WATTS BAR, BELLEFONTE, YELLOW CREEK NUCLEAR PLANTS - REPORTABLE DEFICIENCY - DESIGN REVIEW PROCESS - INTERFACE COORDINATION ACTIVITY - HTRD-50-518/81-17, -519/81-13, -520/81-15, -521/81-13 - PBRD-50-553/81-18, -554/81-12 - WBRD-50-390/81-63, -391/81-59 - BLRD-50-438/81-46, -439/81-49 - YCRD-50-566/81-17, -567/81-14

The subject deficiency was initially reported to NRC-OIE, Region II, Inspector R. V. Crienjak on July 17, 1981 as Audit JA 8100-03 Findings 0-1 and 0-2. Further TVA review of Finding 0-2 concluded that the finding was not significant and should not have been reported to NRC. This conclusion was discussed with and approved by Inspector Don Quick on August 11, 1981.

In compliance with paragraph 50.55(e) of 10 CFR Part 50, this letter constitutes the second interim report on the subject deficiency. TVA is continuing to review the interface coordination requirements and responsibilities as defined in EN DES procedures. We expect to supply you with additional information by December 29, 1981. If you have any questions, please call Jim Domer at FTS 858-2725 for Hartsville and Phipps Bend and Ralph Shell at FTS 858-2676 for Watts Bar, Bellefonte, and Yellow Creek.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

M. Mills, Manager

Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

OFFICIAL COPY