

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

82 JAN 26 1982
January 25, 1982

WBRD-50-390/81-14
WBRD-50-391/81-13

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - IMPROPERLY INSTALLED SUPPORT ANCHORS - WBRD-50-390/81-14, WBRD-50-391/81-13 - SEVENTH INTERIM REPORT

The subject deficiency was reported to NRC-JIE Inspector H. Dance on June 8, 1981 in accordance with 10 CFR 50.55(e) as NCR 3311R. NCR 3311R concerns improperly installed support anchors for the Watts Bar unit 2 reactor building. This is the same type of deficiency and corrective action program as NCR 2789R, which was initially reported to NRC-OIE Inspector M. Thomas on January 7, 1981. NCR 2789R was written for units 1 and 2, and interim reports were submitted on February 6 and June 23, 1981. Since these deficiencies are closely related, TVA has combined both NCR's into one report. Combined interim reports were submitted on July 8, August 13, September 27, and November 24, 1981. TVA is still in the process of reviewing the subject deficiency. We expect to submit our next report by March 30, 1982.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

OFFICIAL COPY

820210285 820125
PDR 7.00CK 05000390
S PDR

IR 27
5/1