

USNRC
TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

83 AUG 23 4 01 35 1983

WBRD-50-390/82-79

WBRD-50-391/82-75

U.S. Nuclear Regulatory Commission
Region II

Attn: Mr. James P. O'Reilly, Regional Administrator
101 Marietta Street, NW, Suite 2900
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

WATTS BAR NUCLEAR PLANT UNITS 1 AND 2 - DEFECTIVE GE TYPE HFA RELAY COILS -
WBRD-50-390/82-79, WBRD-50-391/82-75 - SUPPLEMENTAL FINAL REPORT

The subject deficiency was initially reported to NRC-OIE Inspector D. Quick on July 26, 1982 in accordance with 10 CFR 50.55(e) as NCR WBN EEB 8206. Our final report was submitted on August 26, 1982. We consider 10 CFR Part 21 applicable to this deficiency.

As discussed with NRC-OIE Inspector Linda Watson on July 29, 1983, the date of August 1, 1983 for completion of corrective actions indicated in our final report on this matter was not met. Replacement of the HFA type relays will begin after receipt of the new coils. The corrective action on this matter will be completed by December 15, 1983.

If you have any questions, please get in touch with R. H. Shell at FTS 858-2688.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills
L. M. Mills, Manager
Nuclear Licensing

cc: Mr. Richard C. DeYoung, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, Georgia 30339

8308260067 830817
PDR ADOCK 05000390
S PDR

1983-TVA 50TH ANNIVERSARY

An Equal Opportunity Employer

OFFICIAL COPY

IE 27
1/0