

P.O. BOX 600 Sweetwater, TN 37874

ERT INVESTIGATION REPORT

PAGE 1 OF 2

CONCERN NO: IN-85-853-X02

CONCERN: Manager (name known) tells workers (known) to do things that are not according to TVA procedures.

INVESTIGATION PERFORMED BY: Rana L. Ahmed

DETAILS

Personnel Contacted:

Confidential

Documents Reviewed:

<u>Mechanical Maintenance Procedure</u> - Cranes, Hoists, Operating Training.

- (1) MSE.5.5 Cranes, hoist, operating training.
- (2) AI-6.4 Cranes, hoists, riggings, equipment and control of heavy load.
- (3) HCI-M7 Hazard Control Instruction
- (4) DNP-2-84 Maintenance Request Form

Summary of Investigation

This concern is not substartiated. The documents that were reviewed during this investigation, revealed that the proper corrective action was taken to resolve the concern. This concern was investigated from September 25, 1985 to October 1, 1985.

Findings:

At the initial interview the CI stated that a valve had been accidently dropped and damaged because a repair shop crane malfunctioned. The manager (name known) asked the craftsmen to ERT INVESTIGATION REPORT

PAGE 2 OF 2

CONCERN NO: IN-85-853-X02

DETAILS, continued

Findings:

install the damaged valve in the IPS. The Nuc Power organization was contacted and were questioned as to whether or not they were aware of any situations in which the CI described. Nuc Power provided a copy of a Maintenance Request (#A-529287) which identified valve #2-FCV-67-22B as requiring repair due to the valve being dropped. This valve number was verified by the CI.

Valve #2-FCV-67-22B was installed in the Intake Pumping Station, which started leaking and eroded at the seat and ring joints. a Maintenance Request (MR) was written to repair the valve. The craftsmen (name known) were moving the valve after the repair had been completed, from the west end of the machine shop, (elev. 713') to a truck located at the east end of the shop (elev. 729'). The valve was lifted by a crane approximately 6'-0" to 12 off the floor. When they reached the east end of the shop, a craftsman noticed that the cable of the crane seemed to be frayed at the drum. The foreman (name known) attempted to lower the load, but it fell down to the floor. The valve was damaged and was be installed. unable to Another Maintenance Request (MR)#A-529287, was generated by the Mechanical QC Inspector to repair the valve per the MR instructions and the specification. It was verified during the investigation, that the crane was operated by one of the pipefitters, who was not authorized and/or properly trained to operate the crane. After this incident, a memo was issued stating the proper training required of the craftsmen to operate such equipment. It was also verified by interviewing other craftsmen that the J.F. (Name known) did not ask the crew to fit the damaged valve into the IPS, but the valve was evaluated by the Engineer and was repaired and inspected to the required specifications.

Conclusion:

This concern is not substantiated because the corrective action had been taken, and management did not direct his workers to violate the procedures.

PREPARED BY

gahr -

Report Keinened #Accepted Marten NSES 10/17/85

REVIEWED BY

REQUEST FOR REPORTABILITY EVALUATION

	st No. <u>IN-85-853-X02</u> (ERT Concera No.)	(ID No., if reported)
	u.	achanical Maintenance
Descr	ription of Problem (Attach relate	d documents, photos, sketches, etc.)
	Management tells workers to	do ihings that are not according
	to TVA procedures.	
Reaso	on for Reportability: (Use supp	lemental sheets if necessary)
	This design or construction defi uncorrected, could have affected of the nuclear power plant at an lifetime of the plant.	
	NO X YES If Yes, Explain:	
	and the second	
	AND	
в.	This deficiency represents <u>si</u> the quality assurance program c	gnificant breakdown in any portion of onducted in accordance with the requir
в.	This deficiency represents <u>si</u> the quality assurance program c of Appendix B.	Unducted III according
в.	This deficiency represents <u>si</u> the quality assurance program c	Unducted III according
в.	This deficiency represents <u>si</u> the quality assurance program c of Appendix B.	Unducted III according
	This deficiency represents : sighthe quality assurance program co of Appendix B. No <u>X</u> Yes If Yes, Explai	
	This deficiency represents : sig the quality assurance program co of Appendix B. No <u>X</u> Yes If Yes, Explai OR This deficiency represents a sig approved and released for const conform to the criteria bases s	Unducted III according
	This deficiency represents <u>signature</u> of Appendix B. No <u>X</u> Yes If Yes, Explai <u>OR</u> This deficiency represents a <u>signaperoved</u> and released for const conform to the criteria bases a construction permit.	<u>enificant</u> deficiency in final design a cruction such that the design does not stated in the safety analysis report of
	This deficiency represents : sig the quality assurance program co of Appendix B. No <u>X</u> Yes If Yes, Explai OR This deficiency represents a sig approved and released for const conform to the criteria bases s	<u>enificant</u> deficiency in final design a cruction such that the design does not stated in the safety analysis report of
	This deficiency represents <u>signature</u> of Appendix B. No <u>X</u> Yes If Yes, Explai <u>OR</u> This deficiency represents a <u>signaperoved</u> and released for const conform to the criteria bases a construction permit.	<u>enificant</u> deficiency in final design a cruction such that the design does not stated in the safety analysis report of

REQUEST FOR REPORTABILITY EVALUATION

D. This deficiency represents a <u>significant</u> deficiency in construction of or <u>significant</u> damage to a structure, system or component which will require <u>extensive</u> evaluation, <u>extensive</u> redesign, or <u>extensive</u> repair to meet the criteria and bases stated in the safety analysis report or construction permit or to otherwise establish the adequacy of the structure, system, or component to perform its intended safety function.

No X Yes If Yes, Explain: OR E. This deficiency represents a significant deviation from performance specifications which will require extensive evaluation, extensive redesign, or extensive repair to establish the adequacy of the structure, system, or component to perform its intended safety function. No X Yes If Yes, Explain; IF ITEM 4A, AND 4B OR 4C OR 4D OR 4E ARE MARKED "YES", IMMEDIATELY HAND-CARRY THIS REQUEST AND SUPPORTING DOCUMENTATION TO NSRS. B. Shew 365-4464 ERT Group Manager Phone Ext. This Condition was Identified by: Oth There for 365-4444 Phone Ext.

Acknowledgment of receipt by NSRS

S. Star

Date 10/11/85 Time 1228

TO: Director - NSRS

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # EX-85-048-003

PSF-

Category: 19 Confidentiality: _YES _NO (1&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: A CERTAIN FOREMAN IS ONLY CONCERNED WITH PRODUCTION NOT SAFETY. THE FOREMAN BYPASSES PROCEDURES AND DOES NOT GET PROPER PAPERWORK FIRST. CONSRUCTION CONCERN. NAMES AND DETAILS TO THIS SPECIFIC CASE ARE KNOWN TO QTCOAND ARE WITHELD TO MAINTAIN CONFIDENTIALITY.

Of Their 10/15

NSRS has assigned responsibility for investigation of the above concern to:

ERT /

NSRS/ERT

NSRS

Bue & Sieffer 10/17125



TO: Director - NSRS

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # EX-85-048-004

PSR

Category: 70

Confidentiality: _YES _NO (18++)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

CONCERN: A SUBJOURNEYMAN WAS WELDING ON A PIPE FLANGE IN THE MECHANICAL SHOP WELDING BOOTH. CI DDES NOT WANT TO CAUSE TROUBLE FOR THE SUBJOURNEYMAN, BUT HE FEELS THAT HE SHOULD NOT HAVE BEEN ALLOWED TO WELD ON THE FLANGE. CONSTRUCTION CONCERN NAMES TO THIS SPECIFIC CASE ARE KNOWN TO GTC, AND WITHELD TO MAINTAIN CONFIDENTIALITY.

DA Shew 10/15/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT V

NSRS/ERT

NSRS

OTHERS (SPECIFY)

Julale W

Burne & Siefler 10/0/85

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # EX-85-054-002

PSR

Category: 70

Confidentiality: _YES _NO (I&H)

NUCLEAR SAFETY RELATED YES

Supervisor Notified: ___YES _X_NO

Concern: C/I ASSIGNED TO A SUB-JOURNEYMAN AND HAD NO OPTION BUT TO USE -THE SUBJOURNEYMAN AS A JOURNEYMAN. NUCLEAR POWER CONCERN. C/I HAS NO FURTHER INFORMATION.

There 10/10/05 MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Buce & Siefler 10/11/05

Operations Personnal

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # HI-85-105-001

NUCLEAR SAFETY RELATED YES

Category: 80

Confidentiality: X_YES _NO (I&H)

Supervisor Notified: ___YES _X__NO

Concern: IN THE PAST, IT WAS ALLEGED A COMMON PRACTICE TO "'ACCIDENTALLY" BY-PASS A OC HOLD POINT WITH RESPECT TO CABLE PULLING ACTIVITIES, AND SUBSEQUENTLY COERCE THE INSPECTOR INTO SIGNING THE MISSED HOLD POINT AS WITNESSED. CONSTRUCTION DEPT CONCERN, 1974. THE C/I DECLINED TO PROVIDE FURTHER DETAILS.

ero 10/10/85 DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT NSRS _ BAS

Burne & Leften 10/11/85

Electrical atte

TO: Director - NSRS

TRANSMITTAL NUMBER T50166

PSR

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 3

Concern # IN-85-115-005

-Category: 85 Confidentiality: _YES __NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _NO_ RH

Concern: ATTITUDE OF SUPERVISION (NAMES AND GROUP KNOWN) IS TO GET PAPERWORK COMPLETE REGARDLESS IF INSTALLATION IS RIGHT OR WRONG. NUCLEAR POWER CONCERN. ADDITIONAL INFORMATION IN FILE, WITHHELD DUE TO CONFIDENTIALITY.

NO FOLLOW-UP REQUIRED.

h Their 10/10/

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS



Bun & Surplan . 10/15/P2

TO: Director - NSRS

TRANSMITTAL NUMBER T50166

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 3

Concern # IN-85-115-005

Category: 85 Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _NOTES

Concern: ATTITUDE OF SUPERVISION (NAMES AND GROUP KNOWN) IS TO GET PAPERWORK COMPLETE REGARDLESS IF INSTALLATION IS RIGHT OR WRONG. NUCLEAR POWER CONCERN. ADDITIONAL INFORMATION IN FILE, WITHHELD DUE TO CONFIDENTIALITY.

NO FOLLOW-UP REQUIRED.

Pjr

TO: Director - NSRS

TRANSMITTAL NUMBER T50166

Concern # IN-85-284-001

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Category: 33 Confidentiality: YES NO (IGH)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: PROBLEMS WITH WELD ROD CAUSED BY REPEATED REBAKING/POOR ROD ISSUE PROCEDURE. C-I QUESTIONS THE QUALITY OF WELD RODS: RODS BEING RUSTED & WET AND FLUX BEING BROKEN OFF. THIS HAD BEEN OCCURRING FOR THE LAST 4 1/2 YEARS; UNIT 1 & 2. CONSTRUCTION DEPT. CONCERN. CI HAS NO ADDITIONAL INFORMATION.

FOLLOW-UP NOT REQUIRED.

no 10/19 MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

OTHERS (SPECIFY)

Welding Rod

Burne & Die Jen

PSR

TO: Director - NSRS

TRANSMITTAL NUMBER TSOL64

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-410-003

PSR

Category: 52 Confidentiality: _YES _NO (1&H)

Supervisor Notified: _X_YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: CI EXPRESSED A CONCERN THAT SOME EMBEDDED PLATES AT WBNP ARE "HOLLOW" (DO NOT HAVE ANY CONCRETE IN CONTACT BEHIND THEM). DETAILS KNOWN TO GTC, WITHELD DUE TO CONFIDENTIALTY. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

chin a leter OCT 0 8 1985

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSHS

DTHERE (GRECTEV)

۸

Civil Bunker

Bruse F. Les pen 10/11/

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-439-001

PSE.

Category: 52 Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _YES_

Concern: REDHEADS HAVE BEEN IMPROPERLY ALTERED, BUT MANAGEMENT REFUSED TO TAKE CORRECTIVE ACTION. DETAILS KNOWN TO OTC, WITHELD TO MAINTAIN CONFIDENTIALITY. CONSTRUCTION DEPT CONCERN.

There 10/10/85 DATE MANAGER, ERT

NSRS has assigned r	esponsibility fo	or investigation of	the above concern to	:
ERT /				
NSRS/ERT		and the second second		
NSRS				
OTHERS (SPECIFY)				
Civil		River J. Sist	Jun 11/185	
Cevil webers				

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-629-001

Category: 33 Confidentiality: YES NO (ISH)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: MANAGEMENT (KNOWN) INSTRUCTED CREWS TO KEEP BUSY EVEN IF THEY HAD TO DRILL HOLES. FILL THEM UP, WELD HANGERS, CUT THEM DOWN ETC. CREW WAS GIVEN TWO WEEKS OFF FOR FOLLOWING THESE DIRECTIONS OR ORDERS. THIS HAPPENED OVER A YEAR AGO IN TERRY TURBINE PUMP ROOM @ EL. 692 IN THE AUX BUILDING, UNIT 2. CONSTRUCTION DEPT CONCERN. CI HAS NO MORE INFORMATION.

& There 10/10/15 MANAGER, ERT

NSRS has assigned responsibility for investigation of the above concern to:

ERT V_

NSRS/ERT

NSRS

OTHERS (SPECIFY) OGC

Bure & Siefler 10/11/85-

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-725-X14

Category: 07 Confidentiality: _YES _NO (I&H)

Supervisor Notified: __YES X_NO NUCLEAR SAFETY RELATED _YES_

Concern: WELDER RECERTIFICATION PROGRAM HAD INADEQUATE SUPERVISORY OVERSIGHT: IT COULD HAVE BEEN POSSIBLE FOR A GOOD WELDER TO WELD THE TEST PLATES FOR AN INCAPABLE WELDER. DETAILS KNOWN TO GTC, WITHELD TO MAINTAIN CONFIDENTIALITY.

There 10/10/85

NSRS has assigned responsibility for investigation of the above concern to: ERT _____ NSRS/ERT _____ NSRS _____ OTHERS (SPECIFY) _____ Walking Burne for fight _____ Walking DATE PSR

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-725-X15

Category: 07 Confide

Confidentiality: YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: THE CONTROL OF WELDER RECERTIFICATION TEST PLATES WAS INADEQUATE: TEST PLATES BEGUN BY ONE WELDER COULD HAVE BEEN COMPLETED BY ANOTHER WELDER. DETAIL KNOWN TO QTC- WITHELD TO MAINTAIN CONFIDENTIALITY.

There 10/0/85 MANAGER.

NSRS has assigned responsibility for investigation of the above concern to: ERT _____ NSRS/ERT _____ NSRS _____ OTHERS (SPECIFY) _____ Walking ____ Walking _____ Walking ____ Walking ____ Walking ____ Walking ____ Walk PSF

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-767-001

PSR

Category: 86

Confidentiality: _YES _NO (IGH)

Supervisor Notified: ___YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: TVA'S TOP MANAGEMENT & LINE MANAGEMENT IS IGNORANT OF QUALITY ASSURANCE DEPARTMENT'S FUNCTIONS AND IMPORTANCE. MANAGEMENT IS INTERESTED IN MEETING COST & SCHEDULES. DETAILS KNOWN TO ERT QVC ANY FURTHER INFORMATION WILL COMPROMISE CONFIDENTIALITY.

here 10/10/85 MANAGER, ER

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-793-002

PSP-

Category: 52

Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _YES_

CONCERN: A HOLE WAS MADE IN THE FLO R OVER THE CONTAMINATED LAUNDRY ROOM IN AN IMPROPER MANNER. DETAIL 3 KNOWN TO OTC, WITHELD DUE TO CONFIDENTIALITY. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

Within a Selen OCT. 0 8 1995 MANAGER, ERT DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Construct

Bure f. Surfler 10/17

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned

the indicated category and priority:

Priority: 1

TO: Director - NSRS

Concern / EN-86-316-002 Confidentiality: __YES __NO (I&H)

NUCLEAR SAFETY RELATED YES

251

Category: 58

Supervisor Notified: X YES ___NO

Concern: CI WAS INVOLVED IN REPAIRING A SPECIFIC PIECE OF EQUIPMENT. THE CI LOOKED AT THE VENDOR'S MANUAL AND REALIZED THE WORK PACKAGE DID NOT INCLUDE ALL NECESSARY REPAIR DETAILS THE VENDOR CALLED FOR. PROBLEM WAS PRESENTED TO AN ENGINEER WHO PROCEEDED TO INFORM THE REPAIRMAN THAT HE HAD ALL THE PAPERWORK HE NEEDED RIGHT IN THE WORK PACKAGE. NUCLEAR POWER CONCERN. NAMES AND DETAILS ARE KNOWN TO QTC AND WITHHELD TO MAINTAIN CONFIDENTIALITY.

NO FOLLOWUP REQUIRED.

There plistos

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Obvation a trad

Pullen 10/17 Run

TO: Director - NSRS

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 3

Concern # IN-86-316-003

Confidentiality: _____NO (I

NUCLEAR SAFETY RELATED NO YES

Category: 53

Supervisor Notified: X YES ___NO

Concern: IF THE WORK PACKAGE DISAGREES WITH THE VENDOR'S MANUAL, WORKERS CAN NOT REPAIR ACCORDING TO THE VENDOR'S MANUAL. NUCLEAR POWER CONCERN. CI HAS NO ADDITIONAL INFORMATION.

FOLLOWUP NOT REQUIRED.

er 10.

NS75 has assigned	responsibility for	investigation	of the a	bove coucers	
ERT					
X525/ERT			<i>u</i> .		
X\$75					
OTHERS (SPECIFY)			0	10.0	
Opportune		A.	523	Lippen	DATE
anter					

PSP

TRANSMITTAL NUMBER T50168

N

TO: Director - NSRS

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Concern # IN-86-316-004

Confidentiality: __YES __NO (I&E)

Priority: 3

Category: 86

Supervisor Notified: YES X NO

NUCLEAR SAFETY RELATED NO

CONCETN: SOME SECURITY PERSONNEL WORK BACK TO BACK 16 HOUR SHIFTS. THIS BACK TO BACK SHIFT WORK SOMETIMES OCCURS FOR 3 OR 4 DAYS IN A ROW. NAMES TO THIS SPECIFIC CASE ARE KNOWN TO QTC AND WITHHELD TO MAINTAIN CONFIDENTIALITY. NUCLEAR POWER CONCERN. CI HAS NO FURTHER INFORMATION.

FOLLOWUP NOT REQUIRED.

Of Their 10/15/85

NSRS has assigned responsibility for investigation of the above concern to:

IRI /

NSRS/ERT

NSRS ____

Opentions Control

Buen & Suppen 10/17/P5

TRANSMITTAL NUMBER T50168

TO: Director - NSRS

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Concern # IN-86-316-005-

NUCLEAR SAFETY RELATED YES

Confidentiality: YES NO (ISE)

Priority: 1

Category: 58

Supervisor Notified: X YES NO

CONCETT: A WORK PACKAGE CALLED FOR REMOVING SPECIFIC PARTS FROM A PARTICULAR PIECE OF EQUIPMENT, BUT THE WORK PACKAGE DID NOT COVER REPLACING THEM AFTER THE REPAIR. THE ENGINEER WAS TOLD THAT THE WORK PACKAGE DID NOT CALL FOR REPLACING THE SPECIFIC PARTS. THE ENGINEER SAID, "YOU HAVE AMPLE PAPERWORK TO DO THE JOB". NAMES AND DETAILS TO THE SPECIFICS ARE KNOWN TO QTC AND ARE WITHHELD TO MAINTAIN CONFIDENTIALITY. NUCLEAR POWER DEPT. CONCERN. CI HAS NO MORE INFORMATION.

FOLLOWUP NOT REQUIRED.

On Shers 10/15/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

operations control

Bune P. Suplen 10/17

TO: Director - NSRS TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-86-316-006

Category: 58 Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _YES_

Concern: WORK PACKAGES ARE FREDUENTLY INCOMPLETE, WHEN CHECKED AGAINST VENDER'S MANUALS. NUCLEAR POWER CONCERN. OI HAS NO ADDITIONAL INFORMATION.

Of Their 10/15/85

NSRS has a signed responsibility for investigation of the above concern to:

ERT /

NSRS/ERT

NSRS _____

Operations Control

Bur J. Suffer 10/17/15

TO: Director - NSRS

TRANSMITTAL NUMBER TS0168

ERT has received the Employee concern icentified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-86-315-007

Category: 58 Confidentiality: _YES _NO (18+)

Supervisor Notified: _X YES ____ NO NUCLEAR SAFETY RELATED _ YES_

Concern: ENGINEERING DOES NOT TAKE THE TIME OR EFFORT TO WRITE COMPLETE WORK PACKAGES THAT COMPLY WITH THE VENDOR'S MANUALS. THEY HAVE BEEN SHOWN TIME AFTER TIME THAT THE WORK PACKAGES DO NOT CONTAIN ENOUGH DETAILS TO COMPLETE THE JOB CORRECTLY. NUCLEAR POWER CONCERN. CI HAS NO ADDITIONAL INFORMATION.

On their 10/15/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT V

NSRS/ERT

NSRS

anter

Buce & Jieften 10/17/95

TO: Director - NSRS

TRANSMITTAL NUMBER TS0168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-06-316-X09

PSR

Category: 48 Confidentiality: _YES _ _30 (1843

Supervisor Notified: ___YES _X_NO ___NUCLEAR SAFETY RELATED _YES_

Concern: TVA CANNOT HAVE A SAFE AND ADEGUATE PREVENTIVE MAINTENANCE PROBRAM IF ENGINEERING CONTINUES TO DISREGARD THE VENDOR'S MANUALS FOR EAFETY RELATED EQUIPTENT. NUCLEAR POWER CONCERN. DI HAS NO FURTHER INFORMATION.

Of their 10/15/85

NGRS has assigned responsibility for investigation of the above concern to:

TRT /

NSRS/ERT

VSRS

Reners & Siefler 10/17/85

operations control

TO: Director - NSRS

TRANSMITTAL NUMBER TO164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # PH-85-002-027

Category: 52

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: INSTRUMENTATION TUBING WHICH AHD BEEN CUT SHORT WAS NOT RECUT, BUT WAS IMPRORERLY INSTALLED IN THE FERRULE CONNECTION TO COMPENSATE FOR THE IMPROPER LENGTH. DETAILS KNOWN TO QTC, WITHELD DUE TO CONFIDENTIALITY. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

OCT 0 8 1935 their inter MANAGER. ERT DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Instrument Install

Rous F. Sieglen A/1785

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

Confidentiality: _YES _NO (I&H)

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # PH-85-002-030

-Catagory: 07

Supervisor Notified: ___YES _X_NO ___ NUCLEAR SAFETY RELATED _YES_

COLSERN: CRAFT PERSONNEL WHO WERE CERTIFIED WELDERS AT WENP FAILED TO PASS THE WELDING TEST AT ANOTHER NUCLEAR UTILITY. CI FEELS THAT THIS INDICATES AN INADEQUACY IN TVA TRAINING/TESTING. CONSTRUCTION DEPT CONCERN. CI HAS NO ADDITION INFORMATION.

NO FOLLOWUP REQUIRED.

here 101.5/85 MANAGER

NSRS has assigned responsibility for investigation of the above concern to:

ERT V

NSRS/ERT

NSRS _____

Welding wildus

Burn fe Sugler 10/17/85

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # PH-85-032-001

75E

Category: 55

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES ___NO NUCLEAR SAFETY RELATED _YES_

Concern: SAMPLING PROGRAMS FOR WBNP STRUCTURAL WELDS FOR SUPPORTS. GAMPLING INSPECTIONS FOR SUPPORT WELDS FOR NCRS: BASIS FOR SELECTING THE SAMPLE, AND REPRESENTATIVE SAMPLING ARE QUESTIONABLE. THIS IS A GENERIC CONCERN. CI REQUESTED THIS CONCERN TO BE INVESTIGATED BY ERT (QTC).

Of Their 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT V

NSRS/ERT _____

OTHERS (SPECIFY)

Hange

Bue & Lufter 10/11/65

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 4

Concern # WI-85-072-001

Category: 86

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED NO YES

Concern: C/I REPORTED THAT A QUALITY EMPLOYEE HAD RECEIVED TWO THREATENING TELEPHONE CALLS. (DETAILS TO THE SPECIFIC CASE ARE KNOWN TO QTC AND WITHHELD TO MAINTAIN CONFIDENTIALITY). NUCLEAR POWER CONCERN. C/I HAS NO FURTHER INFORMATION.

Of Their 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT _/_

NSRS/ERT

NSRS _____

OTHERS (SPECIFY) OGC

Bured. Sieflen 10/11/25

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

Confidentiality: _YES _NO (I&H)

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # HI-85-067-001

Category: 80

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: CI EXPRESSED THAT EMPLOYEES ARE AFRAID TO REPORT ANY DAMAGE FOR FEAR OF REPRISAL. TVA IS MORE INTERESTED IN PUNISHING SOMEONE RATHER THAN IDENTIFYING AND CORRECTING A NONCONFORMANCE. NO SPECIFICS KNOWN. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

Within plese OCT 08 1995

MANAGER, ERT

DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

AQ

Bure & Sieflen 10/17/85

TO: Director - NSRS

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified_below, and has assigned the indicated category and priority:

 Priority: 1
 Concern # IN-85-001-005

 Category: 5
 Confidentiality: __YES __NO (I&H)

 Supervisor Notified: YES X NO
 NUCLEAR SAFETY RELATED YES

Concern: VENDOR WELDS WERE BOUGHT OFF EVEN THOUGH THEY EXHIBITED "SHODDY WORKMANSHIP". CONSTRUCTION DEPT. CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

. 10/13 MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS _

Welding

10

TO: Director - NSRS

TRANSMITTAL NUMBER T50168

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-001-007

Category: 19 Confidentiality: _YES _NO (18++)

Supervisor Notifieo: ___YES X_NO ___NUCLEAR SAFETY RELATED _YES___

Concern: THERE HAS BEEN NUMEROUS INCIDENTS OF FAILURE TO FOLLOW PROCEDURES. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

There 10/15/85 MANAGER. ER

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NERS

construct

Bue J. Siefen 14/17/05

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-001-008

Category: 07

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES X_NO NUCLEAR SAFETY RELATED YES_

Concern: 1981 OR 1982. THE QC INSPECTORS WERE GIVEN A VISUAL WELD TEST (AFTER INSPECTION TRAINING) AND APPROXIMATELY 75% TO 80% OF THE QC INSPECTORS ON-SITE FAILED THE TEST. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

There pholos MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ENT

OTHERS (SPECIFY)

Jospection

Burn F. Lieften 10/1/05

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-018-004

A.,

PSR

Category: 52

Confidentiality: YES NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: SUPERVISION (KNOWN) WOULD NOT FOLLOW CABLE PULLING PROCEDURE. THE WORK PROCEEDED WITHOUT PERMITS AS REQUIRED BY PROCEDURE. SUMMER 1984. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

OCT 08 1985 MANAGER. ERT DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

Curbo

Buce & Lief

TO: Director - NSRS

TRANSMITTAL NUMBER T50166

Confidentiality: _YES _NO (I&H)

Concern # IN-85-250-001

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 3

-Category: 19

Supervisor Notified: X_YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: CRAFT (KNOWN) ON SECOND SHIFT WAS REQUESTED TO HAVE PIPE SUPPORTS RE-INSPECTED BY Q.C. AFTER WORK ON THESE HANGERS WAS PERFORMED WITHOUT APPROPRIATE WORK RELEASES. C/I IS NOT CERTAIN WHETHER THESE PIPE SUPPORTS WERE EVER RE-INSPECTED. THIS OCCURRED DURING JAN. OR FEB. 1985 IN REACTOR BUILDING #2 ON PIPE SUPPORTS IN SYSTEM 32 NEAR THE RACEWAY AREA AND ACCUMULATOR ROOMS. CONSTRUCTION DEPARTMENT CONCERN.

There 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS /

How yord

Rome & Light blogs

FSR

TO: Director - NSRS

TRANSMITTAL NUMBER T50166

254

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 3

Concern # IN-85-277-001

-Category: 21 Confidentiality: _YES _NO (I&H)

Supervisor Notified: X_YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: CRAFT (KNOWN) WAS INSTRUCTED BY FOREMAN (NAME KNOWN) TO INSTALL 3" PIPE RUN IN TURBINE BUILDING WITHOUT ANY DESIGN DRAWINGS FROM ENGINEERING IN THE WORK PACKAGE. THIS OCCURRED BETWEEN SEPT. 1983 TO SEPT. 1984. CONSTRUCTION DEPARTMENT CONCERN. C/I COULD NOT PROVIDE ANY ADDITIONAL DETAILS/SPECIFICS.

NO FOLLOW-UP REQUIRED.

Of There 1/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS /

Constructor Construct

Bure & Seefler 1415/85

TO: Director - NSRS

TRANSMITTAL NUMBER TSOIGS

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 4

Concern # IN-85-284-005

Category: 84 Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES X_NO NUCLEAR SAFETY RELATED _NO' BO

Concern: PLANT CLEANLINESS IS POOR. WATER IS ON THE FLOORS. SCAFFOLDS ARE NOT CLEANED OFF, DIRT IS ON PIPES & TRASH IS NOT REMOVED. THIS IS A GENERIC CONCERN - UNIT 1 & 2. CONSTRUCTION DEFT. CONCERN. CI HAS NO FURTHER INFORMATION.

FOLLCW-UP NOT REO'D.

hero pho

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

Construct

Run F. Lespen 0/15

TO; Diffector - NSRS

TRANSMITTAL NUMBER T50167

ENT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-289-001

PSK

Category: 06

Confidentiality: YES NO (I&H)

Superviser Notified: X_YES___NO

NUCLEAR SAFETY RELATED YES

Concern: OPERATORS HAVE ALREADY MADE ERRORS DURING HOT FUNCTIONAL TESTING IN UNIT 1. APPROXIMATELY ONE YEAR AGO (1984) WHICH WOULD HAVE BEEN SIGNIFICANT IF PLANT HAD BEEN OPERATING. CI EXPRESSED CONCERN REGARDING THE INADEQUATE QUALIFICATIONS & TRAINING OF OPERATORS. CI HAS NO FURTHER INFORMATION. CONSTRUCTION DEPT CONCERN.

Then 10/10/15 MANAGER,

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS V

OTHERS (SPECIFY)

Personana)

Bure & Suptim 10/11/15

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 4

Concern # IN-85-289-003

FIG

Category: 52 Confidentiality: _ 7ES _NO (I&H)

Supervisor Notified: X_YES___NO NUCLEAR SAFETY RELATED _YES_

CODCERN: THE REQUIREMENT FOR CABLE TRAY SUPPORTS IS FAR LESS STRINGENT IN THE TURBINT AND CONTROL BUILDING THAN AUX AND REACTOR BUILDINGS. TO PROVE THE POINT, CI STATES THAT CABLE TRAY SUPPORTS IN TURBINE & CONTROL BUILDINGS ARE NOT AS STRONG AS THE SUPPORTS IN AUX & REACTOR BUILDING. CI THINKS THAT SAME EARTHQUAKE IS GOING TO HIT ALL THE BUILDINGS. CI HAS NO MORE INFORMATION.

There 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ---

NSRS/ERT

NSRS V

Brace & Sufferen 10 11/15



TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 4

Concern # IN-85-289-004

PSR

Category: 33

Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: DESIGN CONSISTENTLY CALLS FOR BUTT WELDS ON CONDUIT SUPPORTS BUILT DURING '78 & '79, INSTEAD OF BEVEL WELDS, ALTHOUGH BEVEL WELDS ARE STRONGER DURING AN EARTHQUAKE. CI HAS NO SPECIFICS, CONSTRUCTION DEPT CONCERN.

Oh There works

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Deserver

Buce F. Sugan n/11/25

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-289-006

Category: 52

Confidentiality: _YES _NO (I&H)

Supervisor Notified: X_YES __NO NUCLEAR SAFETY RELATED _YES_

CONCERN: VERMASCO WAS APFLIED TO CABLES PREMATURELY. PENETRATIONS AND CONDUITS WERE BEALED. VERMASCO WAS DETERMINED TO KEEP HEAT IN AND DETERIORATED THE INSULATION. THIS APPLICATION WAS DISCONTINUED 1 1/2 YEARS AGO BUT THE VERMASCO ALREADY APPLIED HAS NOT BEEN REMOVED. BOTH UNITS. CONSTRUCTION DEPT CONCERN. CI HAS NO MORE INFORMATION.

Of their 10/0/15

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

OTKERS (SPECIFY)

Electrical Justail

Bursed Duffen 10/11/85

PSFL

TO: Director - NSRE

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-366-003

PSI-

Category: 58

Confidentiality: _YES NO (ISH)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: HANDLING OF PAPERWORK, RECORDS AND DRAWINGS IS UNSATISFACTORY. TIME SHOULD BE TAKEN TO STUDY THE PROBLEM AND SPEED UP THE PROCESS OF MANAGEMENT DOES NOT LISTEN TO THE ENGINEER'S HANDLING PAPERWORK. RECOMMENDATIONS OF THE ABOVE SUBJECT. CI HAS NO ADDITIONAL. INFORMATION. CONSTRUCTION DEPT CONCERN.

NO FOLLOWUP REQUIRED.

08 1935

MANAGER, ERT

DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT

NSRS/ERT

NSRS

Contral

Bue & Liefton 14/7/8

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-439-002

Category: 52

Contidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES __NO NUCLEAR SAFETY RELATED _YES_

Concern: "HOLLOW" EMBED PLATES- EMBED PLATES THAT, WHEN LIGHTLY TAPPED WITH A HAMMER OR FINGER, SOUND HOLLOW. THIS IS DUE TO THE FACT THAT THERE IS A SPACE BETWEEN THE PLATE AND THE CONCRETE. INDIVIDUAL STATED THAT THESE PLATES EXIST "ALL OVER THE PLACE" IN BOTH UNITS 1 & 2. INDIVIDUAL ALSO STATED THAT THE WORD HAS COME DOWN FROM MANAGEMENT (KNOWN) THAT IF ANYONE IS CAUGHT "TAPPING" EMBED PLATES THEY WOULD BE FIRED. "IF IT DOESN'T FALL, LEAVE IT." EG: 1) AUX BUILDING, 713' EL VERY CLOSE TO DOUBLE DOORS, 10' HIGH ON WALL - NEAR A AND T LINES IN UNIT 1 BEFORE DOORS. 2) GO THROUGH DOORS, LOOK RIGHT, 15'-20' FROM DOOR 12'-14' UP WALL. 3) AUX BUILDING, 726' EL. AT A-13 AND U LINES. HOLLOW EMBEDS AND BAD CONCRETE ABOVE LEDGE. CI HAD NO FURTHER INFORMATION. (CONSTRUCTION DEPT CONCERN)

Is There 10/10/15

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS _____

Civil

Buce I. Siefler 10/11/85

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-85-879-001

Category: 54 Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _NO_FKS

Concern: AN INSPECTION WAS PERFORMED AROUND 1980 OR 1981 IN UNIT 1. ICE CONDENSER, AIR SUPPLY AND RETURN WALL DUCT. THIS INSPECTION REVEALED THAT A NUMBER OF DUCTS WERE BLOCKED/RESTRICTED VARYING FROM 30% TO 100%. THE INSPECTION WAS TERMINATED WITH NO FOLLOW-UP ACTION. CONSTRUCTION DEPT CONCERN. CI HAS NO MORE INFORMATION.

Of their 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

OTHERS (SPECIFY)

Testing

Bun & Diellin 10/11/15

Por

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

Confidentiality: _YES _NO (I&H)

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-86-314-002

Category: 19

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: CABLE PULLING PROCEDURES ARE INADEQUATE. CONSTRUCTION DEPT. CONCERN. C/I HAS NO ADDITIONAL INFORMATION.

here repop MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

OTHERS (SPECIFY) ____

Bune F. Luglin MI

Electrical Cotton

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # IN-86-314-004

Category: 52 Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: CABLE SEPARATION IS INADEQUATE AND IN MANY CASES NONEXISTENT. CONSTRUCTION CONCERN. C/I HAS NO ADDITIONAL INFORMATION.

us phi

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS /

Electrical Install

Bure & Juplin 10/11/25

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # PH-85-002.009

Category: 14

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: C/I IS CONCERNED ABOUT THE USAGE OF PHILLIPS REDHEAD ANCHOR BOLTS FOR ATTACHING ITEMS TO CONCRETE, D 1 TO REDHEADS HAVING BEEN DECLARED UNSUITABLE FOR USE AND REPLACED A. A NUMBER OF OTHER NON-TVA NUCLEAR SITES. CONST. DEPT. CONCERN. C/I HAS NO FURTHER INFORMATION.

Of There apopto

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

and

Bun & Sulfor 10/1/05

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # PH-85-002-026

Category: 52 Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES X_NO NUCLEAR SAFETY RELATED _YES_

Concern: REDHEARD CONCRETE ANCHORS AVE BEEN IMPROPERLY INSTALLED THROUGH WBNP. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

Within a tele OCI 08 1985 MANAGER, ERT DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

OTHERS (SPECIFY)

and and a

Rune & Juglen 10/17/85

PSF.

TO: Director - NSRS

TRANSMITTAL NUMBER-T50164

ERT has received the Employee concern disentified below, and has assigned the indicated category and priority:

Priority: 1

Conce n # PH-85-002-029

-Category: 07

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES

Concern: A JOURNEYMAN CRAFT (ANME AND DISCIPLINE KNOWN) WAS ALLEGED TO BE AN EXAMPLE OF AN UNQUALIFIED CRAFTSMAN WHO CONSITENTLY PERFORMED SUBSTANDARD WORK, WHICH WAS ACCEPTED BY QC. INSPECTOR'S NAME IS NOT KNOWN. CONSTRUCTION DEPT CONCERN. CI HAS NO FURTHER INFORMATION.

NO FOLLOWUP REQUIRED.

MANAGER, ERT

NSRS has assigned responsibility for investigation of the above concern to:

ERT A.

NSRS/ERT

NSRS

OTHERS (SPECIFY)

Welders

Buch Suglen 10/17/PS

FSR

TO: _imector · NSRS

TRANSMITTAL NUMBER T50165

TSE

ERT is received the Employee concern identified relow, and has assigned the indicated category and priority:

Preprity: 1

Concern # PH-85-042-661

Category: 52

Confidentiality: YES NO (I&H)

Supervisor Notified: _X_YES ___NO

NUCLEAR SAFETY RELATED YES

CONCERN: C/I AS A CONCERN THAT THE NUTS USED TO BOAT DOWN THE BORATED WATER TANKS MAY BE INADLOGATE AND THERE MAY NOT B2 A SUFFICIENT CONTACT BETWEEN THE PLATES AND BRACKET. ALSO. WHILE TIGHTENING THESE NUTS, A BOLT TURNED, BECAUSE THE NUT WAS TOO TIGHT. CONST. DEPT. CONCERN. C/I HAS NO FURTHER INFORMATION.

here 10/10/ MANAGER.

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

Bund Lufter 10/11/27

Dequero

TO: Director - NSRS

TRANSMITTAL NUMBER T50165

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # WI-85-065-001

Category: 52

Supervisor Notified: ___YES __NO NUCLEAR SAFETY RELATED YES

Confidentiality: _YES _NO (I&H)

Concern: REACTOR BUILDING #2, RACEWAY (GO DOWN THE AIRLOCK AND TO THE RIGHT, OUTSIDE THE REACTOR) CONDUIT HAS 2'' 66'' HANGERS INSTALLED, AND THE REMAINDER OF THE SUPPORTS ARE WIRE HANGING FROM THE CEILING. THIS WAS DONE DUE TO THE WELDERS HAVING BEEN FURLOUGHED, AND IS STILL IN THE SAME CONDITION AS IT WAS " 4 WEEKS AGO. C/I HAS NO FURTHER INFORMATION.

Of Their 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

Rune & Juffer 10/1/85

Honor Justal

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # XX-85-041-001

Category: 33

Confidentiality: _YES _NO (I&H)

Supervisor Notified: _X_YES ___NO NUCLEAR SAFETY RELATED _YES_

Concern: AT SEQUOYAH, A WELD WAS MADE IN '79 OR '80 IN DIESEL GENERATOR BUILDING, UNIT 1. USING THE WRONG TYPE ROD TO WELD CARBON STEEL PIPE TO STAINLESS STEEL PIPE. A COVER PASS USING THE CORRECT ROD WAS RUN OVER THE EXISTING WELD. CONSTRUCTION DEPT CONCERN. CI HAS NO MORE INFORMATION.

Of Thew 10/10/85

PSR

TO: Director - NSRS

TRANSMITTAL NUMBER T50167

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # XX-85-053-001

Category: 58

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED _YES_

Concern: SEQUOYAH- DOCUMENTATION SAMPLING PLAN FOR PIPE SUPPORTS AND CONDUIT SUPPORTS/WAS INADEQUATE: PLAN ALLOWED ACCEPTING SYSTEMS WITH ONLY 10% OF THE ORIGINALLY REQUIRED DOCUMENTATION. CASES OF MISSING DOCUMENTATION WERE "EVALUATED" AWAY. IN CASES WHERE 10% OF THE DOCUMENTATION WAS NOT FOUND, INSPECTIONS/TESTS WERE ONLY RE-DONE TO THE EXTENT NECESSARY TO REACH 10%. THE CI DOES NOT BELIEVE THIS WAS ADEQUATE, AND MIGHT NOT HAVE MET NRC REQUIREMENTS. (UNIT 1- 1978 TO 1980, CONSTRUCTION ENGINEERING) AUX, CONTROL, & DIESEL GEN. BUILDINGS.

There 10/10/85

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS V

Bue & Sugles 10/11/25

Howard

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 1

Concern # XX-85-053-002

PSE

Category: 11

Confidentiality: _YES _NO (I&H)

Supervisor Notified: ___YES _X_NO NUCLEAR SAFETY RELATED YES

Concern: SEQUOYAH- ENGINEERING EVALUATIONS FOR DOCUMENTATION MISSING ON PIPE SUPPORTS AND CONDUITS SUPPORTS WAS NOT ALWAYS DONE PROPERLY: SOMETIMES THE HARDWARE WAS NOT EXAMINED BEFORE THE EVALUATION WAS MADE. EG IN ONE CASE, THE NRC FOUND A HANGER DOCUMENTED AS BOLTED, BUT IT WAS ACTUALLY WELDED. (CI HAS NO MORE INFORMATION) UNIT 1- 1978 TO 1980 CONSTRUCTION/ENGINEERING - AUX, CONTROL & DIESEL GEN BUILDINGS.

NO FOLLOWUP REQUIRED.

This it defen OCT 08 1935

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

alculationi

Runs & Super 10/17/85

TO: Director - NSRS

TRANSMITTAL NUMBER T50164

ERT has received the Employee concern identified below, and has assigned the indicated category and priority:

Priority: 4

Concern # XX-85-053-X03

Category: 86 Confidentiality: _YES _NO (I&H) Supervisor Notified: __YES _X_NO NUCLEAR SAFETY RELATED _NO GE

Concern: SEQUOYAH- EMPLOYEES FO NOT TRUST MANAGEMENT, BECAUSE MANGERS ARE INEXPERIENCED, THEY ARE NOT PROMOTEDD BECAUSE OF ABILITY, THEY WILL DO ANYTHING THEY RE TOLD WITHOUT QUESTIONING WHETHER IT IS RIGHT OR WRONG, AND THEY DO NOT WORK IN THEIR SUBORDINATES' BEST INTERESTS. THIS LACK OF TRUST WENT SO FAR AS TO AFFECT QUALITY AT SEQOYAH. CI HAS NO MORE INFORMATION. (ENGINEERING- CONSTRUCTION DEPT CONCERN)

NO FOLLOWUP REQUIRED.

William Stehen DCI 0 8 1935

MANAGER, ERT DATE

NSRS has assigned responsibility for investigation of the above concern to:

ERT ____

NSRS/ERT

NSRS

operations control

Bure & Suffer 17/17/85

UNITED STATES GOVERNMENT

TVA 64 (05-9-65)

Memorandum

TENNESSEE VALLEY AUTHORITY

TO E. R. Ennis, Acting Site Director, Watts Bar Nuclear Plant

FROM : K. W. Whitt, Director of Nuclear Safety Review Staff, E3A8 C-K

DATE : OCT 17 1985

SUBJECT: CORRECTIVE ACTION RESPONSE EVALUATION

REPORT NO.	:	IN-85-460-003	9		-
SUBJECT	:	Gouged CC Pipe			20
CONCERN NO.	:	IN-85-460-003			_
129				25	

- () ACCEPT () REJECT
- (X) ACCEPT WITH COMMENT

Action taken as indicated on the NCR 2477R provides adequate documentation of the resolution to the cited problem. This item is closed.

Original signed by M.S. Kidd

K. W. Whitt

Attachment cc (Attachment): H. N. Culver, W12A19 C-K QTC/ERT, Watts Bar Nuclear Plant G. Wadewitz, Watts Bar Nuclear Plant W. F. Willis, E12B16 C-K (4)

0032U

UNITED STATES GOVERNMENT Memorandum


TENNESSEE VALLEY AUTHORITY

TO : <u>K. W. Whitt, Director, Nuclear Safety Review Staff, E3A8 C-K</u> FROM : Guenter Wadewitz, Project Manager, Watts Bar Nuclear Plant OC DATE : SEP 20 1985 SUBJECT: WATTS BAR NUCLEAR PLANT - REQUEST FOR INVESTIGATION/EVALUATION

Attached is our revised response to employee concern number IN-85-460-003.

Guenter Wadewitz

COC:LLE QERT.LE Attachments cc (Attachment): H. N. Culver, W12A19 C-K





Buy U.S. Savings Bonds Regularly on the Payroll Savings Plan

Concern No. IN-85-460-003

NSRS Recommendations: WBNP OC should initiate an NCR on the component cooling system pipe identified in the report in order to obtain resolution and documentation of this issue.

OC Response: After a more thorough investigation of closed NCRs in RIMS, it was revealed that a nonconformance report number 2477R was initiated at the time the gouge was initially reported on July 29, 1980. The gouge was repaired on a base metal repair sheet on August 6, 1980 and filed in the QCRU vault. NCR 2477R was closed on September 4, 1980. See attached.

Principally prepared by Robert R. Kirkpatrick, extension 404.