

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D.C. 20555-0001

October 24, 2008

Vice President, Operations Entergy Operations, Inc. Grand Gulf Nuclear Station P.O. Box 756 Port Gibson, MS 39150

SUBJECT: GRAND GULF NUCLEAR STATION, UNIT 1 – CLOSEOUT OF GENERIC LETTER 2007-01, "INACCESSIBLE OR UNDERGROUND POWER CABLE FAILURES THAT DISABLE ACCIDENT MITIGATION SYSTEMS OR CAUSE PLANT TRANSIENTS" (TAC NO. MD4332)

Dear Sir or Madam:

On February 7, 2007, the U.S. Nuclear Regulatory Commission (NRC) issued Generic Letter (GL) 2007-01, "Inaccessible or Underground Power Cable Failures That Disable Accident Mitigation Systems or Cause Plant Transients" (Agencywide Documents Access and Management System (ADAMS) Accession No. ML070360665). GL 2007-01 requested that licensees provide the following information within 90 days of the date of the GL:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of Section 50.65 of Title 10 of the Code of Federal Regulations (10 CFR 50.65, the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support emergency diesel generators (EDGs), offsite power, emergency service water (ESW), service water, component cooling water, and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

In your letter dated May 4, 2007 (ADAMS Accession No. ML071270171), you provided the information requested in GL 2007-01 including:

- (1) A history of inaccessible or underground power cable failures for all cables that are within the scope of 10 CFR 50.65 (the Maintenance Rule) and for all voltage levels including the cable type, cable manufacturer, date of failure, type of service, voltage class, years of service, and the root causes for the failure; and
- (2) A description of all inspection, testing, and monitoring programs to detect the degradation of inaccessible or underground power cables that support EDGs, offsite power, ESW, service water, component cooling water, and other systems that are within the scope of 10 CFR 50.65 (the Maintenance Rule).

The NRC staff has reviewed the submitted information and has concluded that, for Grand Gulf Nuclear Station, Unit 1, your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please contact me at (301) 415-2296.

Sincerely,

Carl. F. Lyon, Project Manager Plant Licensing Branch IV Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-416

cc: Distribution via Listserv

- 2 -

The NRC staff has reviewed the submitted information and has concluded that, for Grand Gulf Nuclear Station, Unit 1, your response to GL 2007-01 is adequate. Based on this review, your response to GL 2007-01 is considered closed and no further action is requested of you at this time.

If you have any questions regarding this letter, please contact me at (301) 415-2296.

Sincerely,

/RA by Jack n. Donohew for/

Carl. F. Lyon, Project Manager Plant Licensing Branch IV Division of Operating Reactor Licensing Office of Nuclear Reactor Regulation

Docket No. 50-416

cc: Distribution via Listserv

DISTRIBUTION:
PUBLIC
LPLIV r/f
RidsAcrsAcnw_MailCTR Resource
RidsNrrDeEeeb Resource
RidsNrrDorIDpr Resource
RidsNrrDorlLpl4 Resource
RidsNrrLAJBurkhardt Resource
RidsNrrPMFLyon Resource
RidsOgcRp Resource
RidsRgn4MailCenter Resource

ADAMS Accession No: ML082880436 *Previously concurred						
OFFICE	NRR/LPL4/PM	NRR/LPL4/LA	DE/EEEB/BC	NRR/LPL4/BC	NRR/LPL4/PM	
NAME	FLyon X	JBurkhardt*	GWilson	MMarkley Br Stor	FLyon the lor	
DATE	10/21/08	10/16/08	10/2/18	10/24/08	10/20108	

OFFICIAL AGENCY RECORD