

Exelon Generation Company, LLC  
Braidwood Station  
35100 South Route 53, Suite 84  
Braceville, IL 60407-9619

www.exeloncorp.com

August 13, 2008  
BW080077

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D. C. 20555-0001

Braidwood Station, Unit 2  
Facility Operating License Nos. NPF-77  
NRC Docket No. STN 50-457

Subject: Braidwood Station, Unit 2 Inservice Inspection Summary Report

Enclosed is the post-outage summary report (i.e., the 90 day report) for Inservice Inspection examinations conducted during the Braidwood Station, Unit 2 thirteenth refueling outage (A2R13). This report is submitted in accordance with the requirements of the American Society of Mechanical Engineers (ASME) Boiler and Pressure Vessel Code, Section XI, "Rules for the Inservice Inspection of Nuclear Power Plant Components," Article IWA-6200, "Requirements."

Please direct any questions you may have regarding this submittal to Mr. David Gullott, Regulatory Assurance Manager, at (815) 417-2800.

Sincerely,



Bryan Hanson  
Site Vice President  
Braidwood Station

Enclosure: Braidwood Station ISI Outage Report for A2R13

A047  
NER  
Rec'd 9/16/08  
Resubmittal  
(on CD) of  
EIE  
SUBMISSION