



Indian Point Energy Center  
450 Broadway, GSB  
P.O. Box 249  
Buchanan, N.Y. 10511-0249  
Tel (914) 734-6710

October 20, 2008

Re: Indian Point Unit 2  
Docket No. 50-247  
NL-08-166

U.S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555-0001

Subject: **Technical Specification 5.6.7 - Steam Generator Tube Inspection Report - Spring 2008 Refueling Outage**

Reference: Entergy letter NL-06-067 to NRC, "Steam Generator Examination Program Results 2006 Refueling Outage (2R17)," dated June 14, 2006.

Dear Sir or Madam:

Entergy Nuclear Operations, Inc. (Entergy) transmitted to the NRC by the referenced letter a copy of the steam generator tube integrity report for the Indian Point Unit 2 spring 2006 refueling outage. As noted in the referenced letter, the next planned steam generator tube integrity inspection for Indian Point Unit 2 is scheduled for spring 2010. Technical specification, 5.6.7, requires that a report be submitted to the NRC 180 days after the initial entry into Mode 4 following completion of a steam generator program inspection. This letter documents that Entergy was not required to perform any inspection in the spring 2008 refueling outage, and therefore no formal report is required to be submitted in accordance with Technical Specification 5.6.7.

There are no new commitments contained in this letter.

If you have any questions or require additional information, please contact Mr. Robert Walpole, Manager, Licensing at 914-734-6710.

Sincerely,

Robert Walpole  
Manager, Licensing  
Indian Point Energy Center

cc: next page

A001  
NRK

NL-08-166  
Docket No. 50-247  
Page 2 of 2

cc: Mr. Samuel J. Collins, Regional Administrator, NRC Region 1  
Mr. John P. Boska, Senior Project Manager, NRC NRR DORL  
NRC Resident Inspectors Office, Indian Point 2  
Mr. Paul Eddy, NYS Department of Public Service  
Mr. Robert Callender, Vice President, NYSERDA