

IPEC List of 10 CFR 50.75 (g) Areas

1	1986	2	Binder A, Loc. 1	1994	A	80' Maintenance & Outage Bldg	Waste Collection Tank backup into MOB drain line.		
2	1992	2	Binder A, Loc. 2	1994	A	Electrical Tunnel Deluge line to transformer yard - 15'			
3		1-2	Binder A, Loc. 3, and other reports	1994	A	Storm Drains	Addressed in separate program of monitoring		
4		2	Binder A, Loc. 4	1994	A	FSB Alleyway between FSB and PAB, 80'	Resin sluicing from drumming station contaminated the area periodically		
5		2	Binder A, Loc. 5	1994	A	Aux Boiler Feed Pump Alleyway - 15'	Overhead line steam blowout in past		
6		1	Binder A, Loc. 6, & Binder B	1994	A, B	RWST Rock Pad & fill - 80'	Potential leaking transmitter boxes, valve maint, flange leaks		
7		1	Binder A, Loc. 7	1994	A	Hittman shed room door, 70' driveway at CSB	Prior operations and possible spills on concrete and/or blacktop		
8		2	Binder A, Loc. 8	1994	A	Transformer yard at RHR Wall	Disassembly of wall of RHR cells to remove pump motors		Adjacent to storm sewer - 15'
9		Site	Binder A, Loc. 9	1994	A	Non-descript areas outside protected area fence			No data in Binder
10		Site	Binder A, Loc. 10	1994	A	Nuclear Environmental Monitoring Lab & garden			No data in Binder
11			Binder A, Loc. 11	1994	A	Building and Grounds Warehouse			No data in Binder
12		2	Binder A, Loc. 12	1994	A	City Water Tank Fenced Area	Some rad material stored in area		No data in Binder
13		2	Binder A, Loc. 13	1994	A	95' hill and doghouse outside airlock	Ongoing storage of RAM, movement of R/M in and out of VC		
14		1	Binder A, Loc. 6, & Binder B	1994	A, B	Diesel Generator rocks and fill - 80'	Apparently transported from RWST spills		
15		1-2	Binder A, Loc. 15	1994	A	Blowdown line in EDG Bldg - 72', and driveway to Unit 1	Blowdown alt. path to U1 flash tank, failed gasket in EDG, underground leaks		
16		2	Binder A, Loc. 16	1994	A	Fan Bldg alleyway - 78'	Plant vent, valves		
17	1990-92	2	Binder A, Loc. 17	1994	A	MOB/FSB alleyway	Leakage from SFP		Contaminated soil removed
18		2	Binder A, Loc. 18	1994	A	PAB/Boric Acid Bldg (BAB) driveway	RAM movement and scaffold storage		
19		2	Binder A, Loc. 19 & 19a	1994	A	BAB Fence line and North side of BAB	Co-60 and Cs-137 on north shoulder of BAB		
20		2	Binder A, Loc. 20	1994	A	MOB Construction Hill, 80' - 95'	RAM movement in doghouse and 95' hill, RAM storage		
21		2	Binder A, Loc. 21	1994	A	Cargo container at Fire Water Tank			
22			Binder A, Loc. 22	1994	A	Cleanco Trailer	Decon facility stored in trailer		
23		Site	Binder A, Loc. 23	1994	A	Oil Tank Farm steam lines	Cross-contam of steam in condensate feed to boilers. Reliefs, traps, etc.		
24		1	Binder A, Loc. 6, & Binder B	1994	A, B	Outside rollup door at Fuel Handling Facility - 70'	RAM movement		

IPEC List of 10 CFR 50.75 (g) Areas

25		1	Binder A, Loc. 25	1994	A	Acid line in NSB/EDB driveway				
26		1	Binder A, Loc. 26	1994	A	Door 7, 70'	Unit 1 unknown activities, now a release point after clean trash frisking			
27		2	Binder A, Loc. 27	1994	A	FSB Door - 80'	lower level FSB activities			
28		1-2	Binder A, Loc. 28	1994	A	Storm drains in protected area				
29		1	Binder A, Loc. 6, & Binder B	1994	A, B	Unit 2 to Unit 1 Waste Transfer Line	Underground line, potential leaks			
30		Site	Binder A, Loc. 30	1994	A	Oil tank farm storage area	Rad material storage			
31		1	Binder A, Loc. 31, SOR-94-275, SAO Report 94-06	1994	A	Unit 1 Pool leakage	Spent fuel, components, stored in pools; water leakage to underground areas			
32		1-2	EarthTech, Inc. Report, in Binder A	March, 2000	A	Multiple areas evaluated	H.S.A. and ISOCS readings of areas in Binder A and other locations			
33		1-2	DAQ, Inc. Report, in Binder A	April, 2000	A	Multiple areas evaluated	ISOCS results evaluated and DCGLs developed			
34		3	TID 95-002, Decom. Planning	Nov, 1995	C	N/A	Provides decommissioning planning guidance			
35		2	TID-03-003	July, 2003	C	East of IP2 SG Mausoleum	Security construction resulted in excess soil, dumped as fill by SG mausoleum.			
36		2	TID-03-008	Sept, 2003	C	IP2 outside PAB drumming station in alleyway.	Leakage from inside PAB into alleyway. Same location as No. 4 in Binder A.			
37		2	TID-04-006	June, 2004	C	Old Unit 2 Outside Rad Material Storage Area	Evaluation by soil samples of old RM Storage Area			
38		2	TID-04-008	June, 2005	C	N/A	Prospective evaluation of Rad Material Storage Areas			
39		2	TID-04-009	Nov, 2004	C	Unit 2 Yard 8 (Interim LLW Storage Area)	Soil sampling and evaluation of Yard 8			
39-A		2	Gamma spec printouts to support TID 04-009	Sept-Oct, 2004	C	Unit 2 Yard 8 (Interim LLW Storage Area)	Gamma spec printouts and log sheets			
40		3	NSE 79-3-077-WDS	May, 1979	C	Site septic field - south of Unit 3 Security Command Post	Septic fields were dug up and moved to a location near met tower.	Co-60, Cs-134, Cs-137		
40-A	1978	3	Gamma spec printouts related to septic field	1987	C	Septic Field moved and buried near met tower in 1979	Gamma spec printouts taken in 1987	Co-60, Cs-134, Cs-137		
41		3	Email on adequacy of septic field monitoring	Feb, 1999	C	Relocated Septic Field	Memo discussing the adequacy of monitoring the relocated septic field			
42		3	IP-RES-97-256	Dec, 1997	C	Multiple areas evaluated	Memo on implementation of 50.75g requirements. Includes 28 locations			
43		3	IP-RES-94-364	Oct, 1994	C	FSB/PAB/VC interface (Pit)	Recommendations to contain contamination in FSB/PAB/VC Pit area			
43-A		3	IP-RES-93-396	Sept, 1993	C	FSB/PAB/VC interface (Pit)	Soil Sampling plan, pigeon pit area			
44		3	IP-RES-93-515	Dec, 1993	C	Waste Holdup Tank area and FSB/PAB/VC Pit	Soil sampling and evaluation of WHUT and FSB/PAB/VC Pit areas			
44-A		3	Gamma spec printouts and soil results sheets	1993 and 1999	C	Waste Holdup Tank area and FSB/PAB/VC Pit	Gamma spec printouts and soil sample results of "pigeon pit" in 1993 & 1999			

IPEC List of 10 CFR 50.75 (g) Areas

45		1	NRC Inspection Report 94-30	Dec, 1994	C	Unit 1 SFP	Inspection report that discusses the Unit 1 Spent Fuel Pool leakage.			
46		N/A	MOU EPA & NRC, Decommissioning	Oct, 2002	C	N/A	MOU: Decommissioning and Decon of Contaminated Sites			
47		N/A	Draft BTP on Site Characterization	Nov, 1994	C	N/A	Draft BTP from NRC: Site Characterization for Decommissioning			
48	7/31/2000	3	DER-00-1894	Aug, 2000	D	IP3 Fuel Storage Bldg	Leakage from 95' FSB through concrete to soil			
49	1993	3	Information: PWST soil remed. options	1993	E	IP3 Primary Water Storage Tank area	Resrad results and cost of remediation depending on soil volume and dose limit			
50		3	Memo IP-RES-96-120	May, 1996	E	Unit 3 Protected Area	Periodic walkdown of postings related to digging restrictions			
51		3	Memo IP-RES-96-038	Feb, 1996	E	Unit 3 Protected Area	Periodic walkdown of postings related to digging restrictions			
52		3	Memo IP-RES-95-289	Dec, 1995	E	Unit 3 Soils	Assessment of Soil Program Recommendations from 1990 Report			
53		3	Memo IP-RES-95-022	Jan, 1995	E	Unit 3 Soils	IP3- Results of meeting to develop approach to handle contaminated soils			
54		3	Memo IP-RES-94-237	July, 1994	E	Unit 3 Soils	Review of soil remediation plan implementation.			
55		3	Memo IP-RES-93-534	Dec, 1993	E	Unit 3 Soils	Status of soil project, including acceptance criteria, and plan changes.			
56	1993	3	Memo IP-RES-93-525	Dec, 1993	E	IP3 Primary Water Storage Tank area	Status of PWST soil action items			
57	1993	3	Memo IP-RES-93-524	Dec, 1993	E	IP3 Primary Water Storage Tank area	Closeout recommendation for PWST soil action item #4.			
58		3	Memo IP-RES-93-512	Nov, 1993	E	Unit 3	Soil Remediation: Pathway Analysis, Dose Conversion Factors & Limits			
59		3	Memo IP-RES-93-308	July, 1993	E	Unit 3	Preliminary Soil Remediation Plan			
60		3	Handwritten notes	1993	E	Unit 3 RWST, PAB/FSB/VC pit, storm drains	Handwritten sample survey results, data from 1983 - 1993			
61	1993	3	SOR 93-371	July, 1993	E	IP3 Primary Water Storage Tank area	PWST Concrete Pad Contamination, Final Event Report			
62		3	Memo IP-RES-93-215	May, 1993	E	Unit 3	Memo describing requirements for excavation work within the protected area			
63		3	Memo IP-CHM-91-027	Dec, 1991	E	Unit 3 storm drains	Investigation results of storm drain contamination at IP3			
64		3	Memo IPI-91DM-279	Sept, 1991	E	Unit 3 RWST Hill	Report of contaminated soil found at the based of the RWST hill.			
65		3	Memo to File 3-342	March, 1986	E	Unit 3 storm drains	Evaluation of radioactivity in the storm drain system			
66		3	Memo IP-DQ-15839	Dec, 1981	E	Unit 3 storm drains, BIT Cell, FSB/PAB/VC Pit, and the "unfinished room" under the electrical tunnel and PAB	Investigation of contamination identified onsite, and follow-up to 1978 report.			
67	1978	3	Memo from J Kelly to Distribution	Oct, 1978	E	East of PAB doors, RWST area, FSB east wall, and FSB/PAB/VC Pit.	Investigation of contamination identified onsite			

IPEC List of 10 CFR 50.75 (g) Areas

67-A	1978	3	Maps and gamma spec printouts	Sept, 1978	E	East of PAB doors, RWST area, FSB east wall, and FSB/PAB/VC Pit.	Maps and gamma spec printouts to support Memo on site contam in 1978			
68		3	Soil Sample Methodology	~1993	E	N/A	Soil Sampling Methodology for Determination of On-Site Soil Contam.			
69		3	List of soil areas	~1994	E	Multiple areas evaluated	List and map of 20 areas planned for soil sampling on site			
70		3	Memo M. Kerns to File	Oct, 1985	E	Unit 3 storm drains	Results of storm drain sampling and recommendations for future sampling			
71	1996	3	IP-RES-96-014	Jan, 1996	Folder H-1	Protected Area Barrier Mod, Security Gate Soil Excavation	Barrier Mod, Soil Evaluation and Recommendations			
72	1996	3	IP-RES-96-041	Feb, 1996	Folder H-1	Protected Area Barrier Mod, Security Gate Soil Excavation	Soil sample results discussion			
73	1996	3	Screening and Release Forms	Jan-Feb, 1996	Folder H-1	Protected Area Barrier Mod, Security Gate Soil Excavation	Screening and Release forms, with gamma spec reports and surveys			
74		1	Whitman Hydrology Report	July, 1994	Folder H-2	Unit 1 area	Assess groundwater migration pathways for U1 SFP			
75	May, 1999	3	DER-99-1009	June, 1999	Folder H-3	Unit 3 Outage Support Building area	Contamination found in curtain drain around U3 OSB	Co-60, Cs-137		
76	March, 2000	3	Screening and Release Form	March, 2000	Folder H-4	Unit 3 Fire Water Storage Tank	FWST Excavation checked for contamination	Cs-137		
77	March, 2000	3	Screening and Release Form	March, 2000	Folder H-5	Lower Parking Lot	Sewage lift pump in lower parking lot, soil contamination check			
78	April, 1999	3	Memo IP-RES-99-084 & supporting docs	April, 1999	Folder H-6	Outside U3 FSB	Check of soil from excavation outside FSB for severing IP2/3 waste intertie.			
79	March, 1999	3	Screening and Release Form & results	March, 1999	Folder H-7	Intake Structure Sinkhole	Check of soil from intake structure sinkhole			
80	April, 1999	3	Screening and Release Form & results	April, 1999	Folder H-7	RAMS Door 303 Sinkhole	Check of soil from RAMS door 303 sinkhole	Cs-137		
81	May, 1999	3	Screening and Release Form & results	May, 1999	Folder H-8	Sandblasting Area	Check of soil from Sandblasting Area			
82	May, 1999	3	Screening and Release Form & results	May, 1999	Folder H-9	Hazardous Waste Building	Check for soil from excavation near hazardous waste	Cs-137		
83	Aug - Sept, 1999	3	Memos - contract water factory excav.	March - Sept, 1999	Folder H-10	Contractor Water Factory	Memos relating to digging, soil samples, and controls for Cont. Water factory excav.	Cs-137		
84	Aug - Sept, 1999	3	Gamma spec results for soil in excavation	Aug - Sept, 1999	Folder H-10	Contractor Water Factory	Gamma spec results of soil for contractor water factor extension	Cs-137		
85	Aug - Sept, 1999	3	Screening and Release Form & results	Aug-Sept, 1999	Folder H-10	GT-2 Transformer area	Check for soil from excavation near GT-2 and contractor water factory extension	Cs-137		
86	Oct, 1994	3	Memo IP-RES-95-010	Jan, 1995	Folder H-11	31 Main Transformer yard soil	Memo with soil results and dose calcs for soils from 31 Main Transformer soil.	Cs-137		
87	Oct, 1994	3	Gamma spec results & contamination surveys	Oct 1994 - Jan 1995	Folder H-11	31 Main Transformer yard soil	Soil sample results and frisk surveys of excavated soil	Cs-137		
88	Oct, 1994	3	Photos	Oct, 1994	Folder H-11	31 Main Transformer yard soil	Photos of soil and rock excavation	Cs-137		
89	April, 1997	3	IP-RES-97-052, -055, -059, & -075 & supporting surveys, gamma spec & docs	April, 1997	Folder H-12	IP3 50.75g area No. 9, RWST Hill, specifically, FSB Tank Pad Area - Zones 1- 3	Zone 1- footings for elect panel in front of tank pad, Zone 2- conduit trench at base of 95' hill and near FSB driveway, Zone 3- trench spanning driveway connecting Zones 1-2	Cs-137		

IPEC List of 10 CFR 50.75 (g) Areas

90		3	Photos of IP3 50.75g areas 11, 13, 14		Folder H-13	IP3 50.75g areas 11-95' Hill, 13-Admin Bldg, 14- OSB south	Photos of areas			
91		3	Soil Sample results & evaluation calcs		Folder H-13	IP3 50.75g area No. 6, south strip of fuel storage bldg	Soil sample results and comparison to screening level doses	Co-60, Cs-137		
92	Nov, 1999	3	Gamma Spec Report	Nov, 1999	Folder H-13	Soil from telephone pole replacement (99-050)	Gamma spec results - only natural nuclides			
93	Feb, 2000	3	Gamma Spec Report	Mar, 2000	Folder H-13	Soil by staircase to city water valve	Gamma spec results - only natural nuclides			
94	Dec, 1995	3	IP-RES-96-007	Jan, 1996	Folder H-13	Lower Pkg Lot, near disch. canal & OCA fence	Gamma spec results and memo dispositioning soil from excavation	Cs-137		
95	Mar, 1995	3	Soil Sample results & evaluation calcs	Mar, 1995	Folder H-14	FP-MW-PTV Excavation	Gamma spec results and form with calcs	Cs-137		
96	Oct-Dec, 1994	3	IP-RES-95-012	Jan, 1995	Folder H-14	Morpholine Tank Excavation	Memo, gamma spec results, and form with calcs	Cs-137		
97	Dec, 1994	3	IP-RES-95-015	Jan, 1995	Folder H-14	Monitor Tank Line Insulation	Insulation checked for contamination, gamma spec & memo	Cs-137		
98	Dec, 1994	3	IP-RES-95-011	Jan, 1995	Folder H-14	NPS Fabrication Shop excavation	Soil checked for contamination, gamma spec & memo	none plant related		
99	Oct, 1994	3	Surveys and gamma spec	Oct, 1994	Folder H-14	Security Range Site	Soil checked for contamination, gamma spec & micro-R gamma survey	none plant related		
100	Jan, 2000	3	Screening and Release Form	Jan, 2000	Folder H-14	T. Hill Training Bldg Parking Lot	Screening and release form with gamma spec	Cs-137		
101	1990 - 1992	2	IP2 SPF Time History	2005	Binder F	Unit 2 Spent Fuel Pool	Overall time line of known repair history of the U2 SFP			
102	1990 - 1992	2	Draft SAO-132 Report on U2 SFP leak	May, 1992	Binder F	Unit 2 Spent Fuel Pool	SAO-132 report describes initial findings of the SFP leak and and corrective actions	Co-58/60, Cs-134/137, Sb-125		Draft SAO Report, unable to locate full package of information
103	1990 - 1992	2	Comments on root cause of U2 SFP	May, 1992	Binder F	Unit 2 Spent Fuel Pool	Handwritten comments on root cause of U2 SFP report.			
104	1990 - 1992	2	INPO Nuclear Network OE 5298	May, 1992	Binder F	Unit 2 Spent Fuel Pool	OE from Indian Point on the SFP leak			
105	1990 - 1992	2	Radiation Survey of U2 SFP NE Corner	Sept, 1990	Binder F	Unit 2 Spent Fuel Pool	Survey of the portion of the SFP wall in the pool where the leak occurred			
106	1990 - 1992	2	Safety Evaluation No. 92-163-TR	June, 1992	Binder F	Unit 2 Spent Fuel Pool	NSE for temporary repair to the SFP liner using epoxy			
107	1990 - 1992	2	Memo Adolph to Sandler, 6/17/92	June, 1992	Binder F	Unit 2 Spent Fuel Pool	Memo discussing contractor liability for work on U2 SFP that resulted in leakage			
108	1990 - 1992	2	U2 SFP Chemistry	Jan- May, 1992	Binder F	Unit 2 Spent Fuel Pool	Chemistry data log sheet for U2 SFP			
109	1990 - 1992	2	Nuclear Facility Safety Committee minutes	June, 1992	Binder F	Unit 2 Spent Fuel Pool	One page of NFSC Minutes for Meeting No. 378, status of leak in U2 SFP liner			
110	1990 - 1992	2	Photos of U2 SFP liner leak investigation	June, 1992	Binder F	Unit 2 Spent Fuel Pool	Photos of U2 SFP outside wall, soil removal, pool liner repair preparations			
111	1990 - 1992	2	Nuclear Safety Evaluation 92-165-DE	June, 1992	Binder F	Unit 2 Spent Fuel Pool	NSE for Spent Fuel Pool Liner Cover Box for repair of U2 SFP liner			
112	1990 - 1992	2	Tech. Rpt No. 8281, Report No. ME-3802	March, 1993	Binder F	Unit 2 Spent Fuel Pool	Evaluation of corrosion of rebar and strength of concrete in U2 SFP walls			
113	July, 1992	1, 2	Inspection No. 50-247/92-16	July, 1992	Binder F	Unit 1 SFP and Unit 2 SFP	Inspection report that discusses the Unit 1 SFP leakage, and Unit 2 SFP leak			

IPEC List of 10 CFR 50.75 (g) Areas

113	Feb, 2000	2	U2 SG Tube Rupture - Release Summary	Mar, 2000	Binder G	U2 SG tube rupture to steam lines/sec side & atmosphere	Report of dose calcs from various pathways			
114		1	1105145-R0002	Jul, 2002	Folder H-15	Unit 1 pool complex	Study of concrete reinforcement corrosion on the structural integrity of the U1 SFP.			
115	Sept, 1994	3	Memo to 50.75g file	Sept, 2004	Folder H-16	Chlorine Modification	Soil and asphalt samples and evaluation of samples; includes gamma spec.			
116	Aug, 1993	3	Surveys and screening and release forms	Aug, 1993	Folder H-16	95' Hill, new nitrogen tank pad area	Surveys and soil samples of 95' hill near nitrogen tank pad	Nb-95, Cs-137		
117	Mar, 1994	Site	IP-RES-94-130, IP-RES-94-248	Mar - July, 1994	Folder H-16	Drum storage area near warehouse and SG mausoleum	Soil sample results and evaluation.			
118	Sept, 1994	3	IP-RES-94-404, IP-RES-94-405	Nov, 1994	Folder H-16	Service Water Duct Bank	Memos and supporting data for service water duct bank.			
119	March - Oct 1997	3	Memos EP-RES-97-036, -047, -181, -199	March - Oct 1997	Folder H-17	Transformer yard soil due to service water piping mod	Soil in transformer yard, controls, soil sample results, and evaluation.	Cs-137		
120	April - July 1997	3	Memos IP-RES-97-049 and -127	April - July 1997	Folder H-17	U3 Security Command post area; stariway & tree digging	Sample results and recommendations for excavated soil	Cs-137		
121	March, 1997	3	Memo IP-RES-97-033	March, 1997	Folder H-17	U3 Security access facility at access road	Sample results and recommendations for excavated soil	Cs-137		
122	June, 1994	3	Tritium counting cover sheet	June, 1994	Folder H-17	Storm drains B-5 and B-7	2 of 8 samples were for storm drains	H-3		
123	Oct, 1993	3	IP-RES-94-167	May, 1994	Folder H-17	Transformer Yard	Composite soil sample results - typical of environmental levels of contamination			
124	Nov, 1994	3	IP-RES-95-013	Jan, 1995	Folder H-17	Transformer Yard	Asphalt and soil samples - clean			
125	Dec, 1995	3	IP-RES-96-015, -040	Jan, Feb, 1996	Folder H-17	North of Water Factory	Excavation of sink hole and storm drain sediment.	Cs-137		
126	Nov, 1993	Site	JAF Lab Unusual Results Notification	Nov, 1993	Folder H-17	IP Site Perimeter	Soil samples at site perimeter	Cs-137		
127	May '94 - Aug 1997	3	IP-RES-97-037, -075, -179	May 1994 - Sep 1997	Folder H-18	95' Hill asphalt, U3 Security pkg lot, mockup area, FSB roof	Misc soil and asphalt samples			
128	Dec, 1995	3	Screening and Release Form & results	Dec, 1995	Folder H-18	Warehouse Sewage Pit Soil	Soil Sample results			
129	Dec, 1997	3	IP-RES-97-255	Dec, 1997	Folder H-18	Near steps to Middle lot - sewage treatment plant	Asphalt, concrete and soil samples			
130	Oct, 1999	3	RES-99-200	Oct, 1999	Folder H-18	Sponge-Blast material used on turbine crossunder piping	Sponge-Blast material used in R-10; clean			
131	March, 2000	3	Survey form	March, 2000	Folder H-18	Outside Annex and RAMS Bldg	Spill on pavement from bladder from NaOH tank, frisk & smears clean, water had Co-60	Co-60		
132	March - Apr 1994	3	IP-RES-94-129, -141, -163 & DER 94-278	March - Apr 1994	Folder H-19	RWST, IP3 50.75g area No. 10	Characterization of soil in fenced area around RWST	Co-60, Cs-134, Cs-137		
133	Feb, 1998	3	IP-RES-98-027	Feb, 1998	Folder H-20	CST, IP3 50.75g area No. 15	Soil sample results and photos of excavation during electrical conduit work			
134	March, 1997	3	IP-RES-97-045	March, 1997	Folder H-20	Substation C Excavation, IP3 50.75g area No. 16	Soil Sample results from excavation at substation C.			
135	Dec, 1997	3	IP-RES-97-252	Dec, 1997	Folder H-20	West side of turbine hall	Soil samples in prparation for installation of monitoring wells	Cs-137		
136	June - July 1997	3	IP-RES-97-085, -153	June - July 1997	Folder H-20	Near intake structure, north end of Power Conversion Bldg	Soil samples evaluated during sink hole repair			

IPEC List of 10 CFR 50.75 (g) Areas

137	1994	3	photo	1994	Folder H-20	Fire Pump Tank Area	photo of area, IP3 50.75g area No. 20			
138	Feb, 1997	3	IP-RES-97-022	Feb, 1997	Folder H-21	Rad Material Storage Area next to SG Mockup Bldg	Sample results for soil nearby Rad Material Storage Area			
139	July, 1994	3	IP-RES-95-014	Jan, 1995	Folder H-22	Interim Rad Waste Storage Facility	Sample of scabbling dust during prep of the IRWSF	Co-60, Cs-137		
140	1994	3	photo	1994	Folder H-22	Hill from Substation C down to Appendix R Diesel area	photo; IP3 50.75g area No. 26			
141	Nov, 1994	3	IP-RES-94-403	Nov, 1994	Folder H-22	Heater Bay Roof	Replacement of Heater Bay roof; surveys indicated background			
142	March, 1999	3	email on intake structure desilting	March, 1999	Folder H-22	Unit 3 Intake Structure	email describing results of silt analysis and controls	Co-60, Cs-137		
143	April, 1995	3	Gamma Spec reports	April, 1995	Folder H-22	Unit 3 Fuel Storage Bldg, outside	Gamma spec analyses for concrete and for soil outside FSB - contaminated	Co-60, Cs-134, Cs-137		
144	March, 1995	3	Gamma Spec reports	March - April 1995	Folder H-22	Discharge Canal	Check soil from excavation due to oil in disch. canal- not radiologically contaminated			
145	July, 1993	3	IP3-RES-93-331, -360	July - Aug, 1993	Folder H-23	Primary Water Storage Tank area, IP3 50.75g area No. 25	PWST soil contamination and remediation, with photos	Co-60, Cs-134, Cs-137		
146	July, 1993	3	SOR 93-371	Dec, 1993	Folder H-23	Primary Water Storage Tank area, IP3 50.75g area No. 25	PWST soil contamination, with photos, surveys, and other backup documentation	Co-60, Cs-134, Cs-137		
147	1979	3	Septic Field Removal; memos, NSE, other	1979	Folder H-24	Septic Field moved and buried near met tower in 1979	Septic Field moved and buried near met tower in 1979	Co-60, Cs-134, Cs-137		
148	April, 2003	3	Backup SFP Cooling System Action Plan	April, 2003	Folder H-25	On and next to Monitor Tank Pad on driveway to FSB	Leak onto MT pad and onto driveway next to pad	Co-58/60, Cs-134/137, others		
149	July - Aug 1994	3	IP-RES-94-279	Aug, 1994	Folder H-26	Appendix R Diesel	Soil sample results and recommendations for App R Diesel & gunnite on hill.	Cs-137		
150	May, 1999	3	Screening and Release Form	May, 1999	Folder H-26	Appendix R Diesel	Soil samples and gamma spec for soil near App R Diesel, contaminated	Cs-137		
151	1991	3	SOR-91-3-86 and other supporting docs	Jan, 1992	Folder H-27	IP3 storm drains	SOR, memos, data, surveys and evaluation of storm drains, also see items 63 - 66			
152	1978	3	Sample analysis sheets and surveys	July - Sept 1978	Folder H-27	Unfinished room, outside contractor control pt, others	Misc surveys and sample results			
153	Oct, 1978	3	Handwritten report and gamma specs	Oct, 1978	Folder H-27	Outside PAB doors, contamination event	Contamination found outside PAB; results of investigation			
154	1993	3	IP-RES-93-378	Sept, 1978	Folder H-28	Waste Holdup Tank Pad and nearby areas	Sampling locations for soil near Waste Holdup Tank area			
155	5	2	CR-IP2-2005-3986	5-Oct-05	Folder H-	Monitoring well 111 IP2	Transformer Yard, sample indicated 2.11E-4 uCi/cc tritium. No other activity identified.	H-3		
156	200-2006	2	CR-IP2-2006-01682	4/10/2006	Folder H	IP-2 RWST Area	Aux Condensate drained to the ground because the steam trap did not work properly.	H-3	14,400 gallons/year	
157	9/1/2005	2	CR-IP2-2005-03557	9/1/2005		IP-2 FSB below floor grade	at approximately 60 foot level of Unit 2 spent fuel pool south wall on the loading bay side.	134, Co-60 & Sr-90	collection rate upto 2 Li/Day.	
158	9/26/2006	3	CR-IP3-2006-02997	9/26/2006	Folder H	IP-3 monitor tank lines.	collected from insulation on IP-3 monitor tank lines. Covering removed from line leading to			
159	4/11/2006	2	CR-IP2-2006-01896	4/19/2006		IP-2 Supplemental Spent Fuel Pool Cooling System	System Secondary side Tritium contamination & leakage. 200 Gallons of 20,000 pico Ci/L			
160	12/5/2006	3	CR-IP3-2006-03818	12/5/2006		IP-3 BUSFPCS Leak	protection. Less 1 gal. leak total. One water sample 1E-7uCi/cc Co-60. Non detect HTO.	Co-60 HTO	1 gal	

IPEC List of 10 CFR 50.75 (g) Areas

161	2/20/2007	2	CR-IP2-2007-00921	2/20/2007	IP2 FSB PW-612/613 Leak	under what is to be the concrete floor of the truck bay area. This CR was written because	Cs-137 Co-60 HTO	< 10 gal	
162		2	CR-IP2-2007-02551	7/13/2007	Utility tunnel	Fixed contamination became loose.	Cs-137	unk	The following RP surveys were conducted to support the initial investigation and posting change: 07-2-1200 on 6/19/07, 07-2-1208 on 6/21/07
163		1	CR-IP2-2007-02551	7/13/2007	Containment Spray Sump Unit 1 15'	Fixed contamination	Cs-13, Sr-90	unk	
164		1	CR-IP2-2007-02551	7/13/2007	5' elevation floor by Outlet Piping	Fixed contamination	Cs-13, Sr-90	unk	