

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | | |
|---|--|---|--|
| 1. LICENSEE/LOCATION INSPECTED: Mid American Inspection Services, Inc. P. O. Box 1427 Gaylord, MI 49735 | | 2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351 | |
| REPORT NUMBER(S) | | | |

| | | |
|---|---|---|
| 3. DOCKET NUMBER(S) 030-31160 | 4. LICENSEE NUMBER(S) 21-26060-01 | 5. DATE(S) OF INSPECTION April 14, 2009 |
|---|---|---|

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:


- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|-----------------------|--|----------------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | Robert P. Hays |  | 4/14/09 |

789

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | | |
|--|--|--|--|
| 1. LICENSEE Mid American Inspection Services, Inc. | | 2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road, Suite 210 Lisle, IL 60532 | |
| REPORT NUMBER(S) 2009-001 | | | |
| 3. DOCKET NUMBER(S) 03031160 | 4. LICENSE NUMBER(S) 21-26060-01 | 5. DATE(S) OF INSPECTION April 14, 2009 | |
| 6. INSPECTION PROCEDURES USED 87121 (8/22/05) | | 7. INSPECTION FOCUS AREAS 03.01-03.07 | |

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|------------------------------------|-------------------------|--|--|
| 1. PROGRAM CODE(S) 03310 | 2. PRIORITY 1 | 3. LICENSEE CONTACT Terry Wilkins, RSO | 4. TELEPHONE NUMBER 989-732-8059 |
|------------------------------------|-------------------------|--|--|

Main Office Inspection Next Inspection Date: **April 2010**

Field Office _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

The licensee is authorized by their license to conduct industrial radiography at temporary job sites. The licensee is authorized to possess and use industrial radiographic equipment and isotopes as sealed sources approved in the sealed sources and devices registry. The licensee is a midsize industrial radiography program and licensed material is used frequently. Only radiographic exposure devices (REDs) containing Ir-192 are used at temporary job sites. The licensee also possesses a sealed source for survey instrument calibrations and a low curie Pipeliner. No change in RED inventory since the previous inspection. Industrial radiography was being conducted at the time of the inspection at a local temporary jobsite (natural gas pipeline installation) off Spar Road, within 10 miles of Gaylord, MI. The inspector attempted to find the radiographers for an inspection at the temporary jobsite, but could not locate the crew. Surveys of the REDs in storage at the main office indicated no dose concerns and consistent with licensee survey records and postings.

Performance Observations

The licensee's RSO demonstrated/discussed: (1) DOT requirements; (2) dosimetry (whole body, pocket, alarming rate meters); (3) survey instrumentation and calibrations; (4) radiographic equipment inspections; (5) security of REDs; (6) utilization logs; (7) radiographer's certifications; (8) source exchanges; (9) staff training; (10) DU leak tests/inventories; (11) staff changes; (12) radiographer audits; and (13) incidents or events with REDs (none).

781