



Indian Point Energy Center
450 Broadway, GSB
P.O. Box 249
Buchanan, N.Y. 10511-0249
Tel (914) 734-6700

Robert Walpole
Manger
Licensing

NL-09-125

September 24, 2009

ATTN: Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001

SUBJECT: Technical Specification 5.6.8 – IP3 Steam Generator Tube Inspection
Report - Spring 2009 Refueling Outage
Indian Point Unit No. 3
Docket No. 50-286
License No. DPR-64

Dear Sir or Madam:

Technical Specification, 5.6.8, requires that a report be submitted to the NRC 180 days after the initial entry into Mode 4 following completion of a steam generator program inspection. This letter documents that Entergy Nuclear Operations, Inc. was not required to perform any inspection in the spring 2009 refueling outage, and therefore no formal report is required to be submitted in accordance with Technical Specification 5.6.8.

The next planned steam generator tube integrity inspection for Indian Point Unit 3 is scheduled for spring 2013, Refueling Outage 3R17. The previous inspection was performed during the spring 2007, Refueling Outage 3R14.

There are no new commitments contained in this letter. If you have any questions or require additional information, please contact me at 914-734-6710.

Sincerely,

A handwritten signature in black ink, appearing to read "RW/mb".

RW/mb

cc: next page

ADD
NRK

cc: Mr. S. J. Collins, Regional Administrator, NRC Region I
Mr. J. Boska, Senior Project Manager, NRC, NRR, DORL
Mr. S. Aguilar, Material Control and Accounting Branch, NRC
NRC Resident Inspectors Office, Indian Point
Mr. Paul Eddy, NYS Dept. of Public Service
Mr. Francis J. Murray, Jr., President and CEO, NYSERDA