



U.S. Nuclear Regulatory Commission Licensee Event Report (LER) Search

[Privacy/Security](#) [Home](#) [Search](#)

[Contact Us](#) [Login](#)

[Return to Previous Search](#)

Displaying **1** to **101** of **101** Records

LER Number	Event Date	Plant	Title
2191989001	01/11/1989	Oyster Creek	Possible Loss of Main Steam Line Isolation Capability Due to Excessive Main Steam Isolation Valve Control Air Leakage
2371980029	07/28/1980	Dresden 2	
2371981004	01/14/1981	Dresden 2	
2371981019	04/26/1981	Dresden 2	
2371981022	05/03/1981	Dresden 2	
2441983028	09/16/1983	GINNA	CVCS Boric Acid System Leakage
* 2441994009	08/09/1994	GINNA	Safety Injection Pumps Declared Inoperable Due to Leak, Causes Condition Prohibited by Technical Specifications and Completion of Plant Shutdown Required by Technical Specifications.
2471980004	05/12/1980	Indian Point 2	
2471983017	04/22/1983	Indian Point 2	Leak in Containment Isolation Valve Seal Water System
2471983032	08/06/1983	Indian Point 2	Leak in Safety Injection Pipe
2491980038	10/21/1980	Dresden 3	
2491983035	10/04/1983	Dresden 3	Leakage from "A" Recirc Pump Bowl Drain Line
* 2491997012	11/01/1997	Dresden 3	Reactor Recirculation B Loop, High Pressure Flow Element Venturi Instrument Line Steam Leakage Results in Unit 3 Shutdown Due to Fatigue Failure Of Socket Welded Pipe Joint
* 2491999003	03/21/1999	Dresden 3	Supplement to Reactor Recirculation B Loop, High Pressure Flow Element Venturi Instrument Line Steam Leakage Results in Unit 3 Shutdown Due to Fatigue Failure of Socket Welded Pipe Joint
2492002003	10/08/2002	Dresden 3	Reactor Recirculation Loop "A" Sensing Line Socket Weld Vibration Fatigue Failure
2492002006	12/07/2002	Dresden 3	Reactor Recirculation Loop "A" Sensing Line Socket Weld Failure
* 2501993002	01/15/1993	Turkey Point 3	REACTOR COOLANT SYSTEM PRESSURE BOUNDARY LEAKAGE; TECHNICAL SPECIFICATION REQUIRED SHUTDOWN
* 2512008003	08/07/2008	Turkey Point 4	Class 1 Weld Leak due to Fatigue and Completion of Technical Specification Required Shutdown
2541983017	04/12/1983	Quad Cities 1	RHR Service Water Hose Coupling Broke
* 2542003001	05/20/2003	Quad Cities 1	Reactor Shutdown Due to Reactor Heat Vent Steam Leak Constituting Pressure Boundary Leakage
2551982020	06/23/1982	Palisades	Incorrect Valve Installed
2551982022	07/30/1982	Palisades	Improper Valve Installed
2551984016	08/10/1984	Palisades	Primary Coolant System - Unidentified Leakage >1 gpm
2551998009	05/31/1998	Palisades	"LEAKS IN ASME CLASS 1 PRIMARY COOLANT SYSTEM SAMPLE LINE WELDS"
2552005005	09/01/2005	Palisades	Reactor Protection System and Auxiliary Feedwater System Actuation
2591985001	01/21/1985	Browns Ferry 1	Unidentified Leakage In Drywell
2631980028	08/25/1980	Monticello	
2631983008	04/13/1983	Monticello	Feedwater Extraction Steam Line Leaks

2661982015	09/14/1982	Point Beach 1	A High Stress Low Cycle Failure of a Lap Joint Flange Stub piece Resulted in an Offsite Gaseous Release
2691982004	02/17/1982	Oconee 1	Reactor Coolant System Normal Makeup Line Weld Radiography Test Indicated a Void
2711981011	05/07/1981	Vermont Yankee	
2711981016	06/22/1981	Vermont Yankee	
2721980065	12/18/1980	Salem 1	
2782005003	09/20/2005	Peach Bottom 3	Residual Heat Removal System Small Bore Piping Leak due to Weld Deficiency
2891981001	01/17/1981	Three Mile Isl 1	
2891982002	01/28/1982	Three Mile Isl 1	Cracking Discovered in the Heat Affected Zone of Two Socket Welds of the Waste Gas Disposal System
2931982047	10/08/1982	Pilgrim	Improper Fabrication During Original Construction
2931985004	02/15/1985	Pilgrim	Vessel Drain Line Leaks
2931986006	03/16/1986	Pilgrim	Weld Leak on Reactor Water Level Instrument Line
2981982006	03/22/1982	Cooper Station	Failed Ductwork
3021983048	10/26/1983	Crystal River 3	Two Inoperable Makeup Pumps
3021985015	08/20/1985	Crystal River 3	Main Turbine Drain Line Break Results in Anticipatory Reactor Trip
3051983028	10/28/1983	Kewaunee	Charging Pump Removed from Service
* 3111990005	01/17/1990	Salem 2	Tech. Spec. 3.0.3 Entry; Two ECCS Subsystems Inoperable
3121982034	12/03/1982	Rancho Seco	
* 3131989010	05/17/1989	Arkansas 1	Reactor Shutdown Due to a Non-Isolable Leak in a Reactor Coolant System Strength Boundary Caused by a Weld Defect
3151980023	09/16/1980	Cook 1	
3161982081	09/30/1982	Cook 2	
3171982074	11/27/1982	Calvert Cliffs 1	Failure of the Pump Discharge Line
3181980018	03/11/1980	Calvert Cliffs 2	
3181981032	07/04/1981	Calvert Cliffs 2	
3181981035	07/03/1981	Calvert Cliffs 2	
3181983024	04/18/1983	Calvert Cliffs 2	Charging Pumpf Removed from Service
3181983077	12/21/1983	Calvert Cliffs 2	Charging Header Drain Line Leaks
3211997001	01/29/1997	Hatch 1	Pressure Boundary Leakage Results in Condition Prohibited by the Technical Specification
3212008001	03/06/2007	Hatch 1	Leak in Reactor Pressure Boundary Piping due to a Crack Caused by Intergranular Stress Corrosion Cracking
3231994001	03/28/1994	Diablo Canyon 2	UNIT SHUTDOWN DUE TO AN UNISOLABLE REACTOR COOLANT SYSTEM LEAK
3331983054	11/04/1983	Fitzpatrick	HPCI Vent Line Cracks
3331991019	09/17/1991	Fitzpatrick	HIGH COOLANT INJECTION INSTRUMENT LINE FAILURE
* 3341995006	08/18/1995	Beaver Valley 1	Pressure Boundary Leakage Results in Plant Shutdown
3351980017	04/28/1980	St Lucie 1	
* 3351997005	04/19/1997	St Lucie 1	Reactor Shutdown Required by Technical Specifications due to Reactor Coolant Pressure Boundary Leakage
3361980027	07/29/1980	Millstone 2	
3361981002	01/03/1981	Millstone 2	
3361981008	02/13/1981	Millstone 2	

* 3362002004	08/03/2002	Millstone 2	Reactor Shutdown Due to Entry into Technical Specification 3.0.3
* 3411991004	03/12/1991	Fermi 2	MANUAL SCRAM DUE TO LOSS OF CONDENSER VACUUM
* 3521987048	09/19/1987	Limerick 1	Reactor Scram Resulting from a Main Turbine Trip due to Low Electro-Hydraulic Control Pressure
* 3541989026	12/31/1989	Hope Creek	REACTOR RECIRCULATION SYSTEM INSTRUMENT LINE LEAKAGE RESULTS IN MODE CHANGE TO COLD SHUTDOWN AS REQUIRED BY TECHNICAL SPECIFICATIONS -EQUIPMENT FAILURE DUE TO INSTALLATION DEFICIENCY
* 3641991002	04/09/1991	Farley 2	Reactor Manually Tripped Following Loss of Steam Generator Feed Pump
* 3641995005	06/01/1995	Farley 2	Manual Reactor Trips Following a Loss of Electro- Hydraulic Fluid
* 3661987010	08/19/1987	Hatch 2	Failed Instrument Line Leakage Exceeds Allowable Limits Resulting In Reactor Shutdown
3662007004	03/09/2007	Hatch 2	Leak in Reactor Pressure Boundary Due To Failure of a Socket Weld
3681980019	04/10/1980	Arkansas 2	
* 3681988011	08/01/1988	Arkansas 2	Unisolatable Reactor Coolant System Leak Caused By Vibration Induced Fatigue Failure of A Reactor Coolant Pump Seal Instrumentation Line
3691981124	07/25/1981	McGuire 1	
3701984017	08/05/1984	McGuire 2	Pipe in Auxiliary Letdown System Damaged By Water Hammer
3731982129	10/18/1982	LaSalle 1	
3731982153	11/18/1982	LaSalle 1	
3731982160	11/24/1982	LaSalle 1	
3731983028	03/20/1983	LaSalle 1	Steam Jet Injection Drain Line Leaks
3821988022	05/23/1988	Waterford 3	Missed Penetrant Test on two Welds Due to Personnel Error
* 3822000003	03/06/2000	Waterford 3	Shutdown Per TS LCO 3.0.3 Due to Cracked Weld Which Rendered the Charging System Inoperable
3882005001	03/20/2005	Susquehanna 2	Degradation of Primary Coolant Pressure Boundary due to Recirculation Pump Discharge Valve Bonnet Vent Connection Weld Flaw
3891983071	11/08/1983	St Lucie 2	Charging Pump Discharge Line Has a Pin Hole Leak
* 3892007001	08/18/2007	St Lucie 2	Reactor Shutdown due to Unidentified RCS Leakage
* 3892008001	01/29/2008	St Lucie 2	RCP 2B1 Upper Seal Cavity Line Leak
3971998015	08/08/1998	Columbia	Discovery of Reactor Coolant Pressure Boundary Leak During Shutdown Conditions
* 4131998010	06/24/1998	Catawba 1	Pinhole Leak in Auxiliary Feedwater Nozzle Tempering Line Causes Noncompliance With Technical Specification Structural Integrity Requirements
* 4231994012	09/09/1994	Millstone 3	Reactor Coolant System Pressure Boundary Leak Due to Instrument Line Socket Weld Failure
* 4231995019	12/01/1995	Millstone 3	Reactor Coolant System Pressure Boundary Leak Due to Instrument Line and Drain Line Socket Weld Failure
* 4241989004	01/19/1989	Vogtle 1	REACTOR COOLANT PRESSURE BOUNDARY LEAKAGE LEADS TO UNIT SHUTDOWN
* 4251994005	07/23/1994	Vogtle 2	PRESSURE BOUNDARY LEAKAGE FOUND FOLLOWING UNIT SHUTDOWN
* 4252005003	12/10/2005	Vogtle 2	Reactor Coolant System Leakage Leads to Shutdown Required by Technical Specifications
* 4541988010	11/05/1988	Byron 1	SAFETY INJECTION ACCUMULATOR FILL LINE BREAK DUE TO FATIGUE REQUIRING PLANT SHUTDOWN PER TECHNICAL SPECIFICATIONS
4581997002	05/06/1997	River Bend	Through-Wall Linear Indication in a Weld on a Reactor Recirculation System Vent Valve
4822003004	11/17/2003	Wolf Creek	FAILURE OF SAFETY INJECTION ACCUMULATOR VENT LINE

- * **4992005001** 02/09/2005 South Texas 2 Shutdown of STP Unit 2 due to Reactor Coolant System Pressure Boundary Leak
- * **5281987018** 08/27/1987 Palo Verde 1 Reactor Trip Occurs During Shutdown Due to Pressure Boundary Leakage
- 5281996006** 10/29/1996 Palo Verde 1 Cracked Weld on HPSI Minimum Recirculation Line Forces TS LCO 3.0.3 Entry
- * **5282004001** 02/03/2004 Palo Verde 1 Reactor Shutdown Due to Reactor Coolant System Pressure Boundary Leakage

Search Restrictions:

Status: Active, Cancelled, Restricted
Event Dates: between Jan-01-1980 and Dec-31-2009
Keyword(s): socket weld
Sorted By: LER Number
Results Per Page: All
Date of Search: Oct-05-2009

This web site is maintained for the U.S. Nuclear Regulatory Commission by the [Idaho National Laboratory](#)

ti: 02:14:28P

* Note: caused plant shutdown.