

POWER AUTHORITY OF THE STATE OF NEW YORK

10 COLUMBUS CIRCLE NEW YORK, N. Y. 10019

(212) 397-6200

TRUSTEES

JOHN S. DYSON  
CHAIRMAN

GEORGE L. INGALLS  
VICE CHAIRMAN

RICHARD M. FLYNN

ROBERT I. MILLONZI

FREDERICK R. CLARK



December 4, 1979  
IPN-79-87

GEORGE T. BERRY  
PRESIDENT & CHIEF  
OPERATING OFFICER

JOHN W. BOSTON  
EXECUTIVE VICE  
PRESIDENT & DIRECTOR  
OF POWER OPERATIONS

JOSEPH R. SCHMIEDER  
EXECUTIVE VICE  
PRESIDENT & CHIEF  
ENGINEER

LEROY W. SINCLAIR  
SENIOR VICE PRESIDENT  
& CHIEF FINANCIAL  
OFFICER

THOMAS R. REY  
SENIOR VICE PRESIDENT  
& GENERAL COUNSEL

Director of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

Attention: Mr. Albert Schwencer, Chief  
Operating Reactors Branch No. 1  
Division of Operating Reactors

Subject: Indian Point 3 Nuclear Power Plant  
Docket No. 50-286  
Pressurizer Weld L-1


Dear Sir:

In accordance with the provisions of Facility Operating License No. DPR-64, Amendment No. 16 (August 11, 1978), License Condition 2.C.4, attached please find ten (10) copies of a report entitled, "Second Refueling Outage Inservice Inspection of Pressurizer Weld L-1". This report demonstrates that there has been no change in the Pressurizer Weld L-1 indication.

License Condition 2.C.4 requires that the Authority receive NRC approval of the results of this ultrasonic examination of Pressurizer Weld L-1 prior to the return to power operation following the current refueling outage. It is hereby requested that NRC approval be received no later than December 14, 1979 in order not to affect the Authority's schedule for the return to power of the Indian Point 3 facility.

If you have any questions on this report, please contact us.

Very truly yours,

  
Paul J. Early  
Assistant Chief Engineer-Projects

Appl  
S. 11  
8001150 509