



J. Phillip Bayne
Executive Vice President
Nuclear Generation

September 7, 1983
IPN-83-79

Dr. Thomas E. Murley, Regional Administrator
U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Indian Point 3 Nuclear Power Plant
Docket No. 50-286
Inservice Inspection Summary and
Final Reports for the Cycle 3/4 Refueling Outage

Dear Sir:


Attached for your information are five (5) copies of each of the following documents:

- (1) A summary report of the inservice inspection activities performed during the cycle 3/4 refueling outage. The report consists of information extracted from Tabs A, B, and C of the Final Weld and Component Examination Inservice Inspection Report.
- (2) WCAP-10222 entitled "Third Inservice Surveillance Examination of the Indian Point No. 3 Steam Generator Channel Head Cladding." Submittal of this report fulfills the requirements of Item 3.7 in Table 4.2-1 of the Indian Point 3 Technical Specifications.

A047
1/1

Should you or your staff have any questions regarding this matter, please contact Mr. P. Kokolakis of my staff.

Very truly yours,

A handwritten signature in black ink, appearing to read "J.P. Bayne". The signature is fluid and cursive, with the first letters of the first and last names being prominent.

J.P. Bayne
Executive Vice President
Nuclear Generation

cc: Resident Inspector's Office
Indian Point Unit 3
U.S. Regulatory Commission
P.O. Box 66
Buchanan, New York 10511

Mr. S.A. Varga, Chief
Operating Branch No. 1
Division of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555