



**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**

1. LICENSEE <b>Twin Ports Testing</b> REPORT NUMBER(S) 2009-001		2. NRC/REGIONAL OFFICE <b>Region III</b>	
3. DOCKET NUMBER(S) 03022241	4. LICENSE NUMBER(S) 48-23476-01	5. DATE(S) OF INSPECTION November 9, 2009	
6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT David Rands	4. TELEPHONE NUMBER 715/392-7114
-----------------------------	------------------	------------------------------------	-------------------------------------

Main Office Inspection      Next Inspection Date: 11/2010

Field Office \_\_\_\_\_

Temporary Job Site \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a radiographer located in Superior, Wisconsin, an Agreement State, with authorization to use material at temporary job sites where the NRC maintains jurisdiction. The licensee was inspected at the office in Superior, Wisconsin and by phone at a temporary job site in North Dakota. This licensee has three certified radiographers and possesses three 660B cameras loaded with iridium-192 sources.

**Performance Observations**

At the time of the inspection, licensee was performing radiography at a temporary job site in the Dakotas. Personnel conducting operations at the temporary job site were interviewed by phone. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel at the main office that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection. Survey instruments were determined to be within calibration as were pocket dosimeters and alarming rate meters.

During calendar year 2008, to date, dosimetry records indicated that no one exceeded 1.5 Rem in exposure for the year.

No violations of requirements were noted.

