


Carl L. Newman
Vice President

Regulatory Docket File


Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N. Y. 10003
Telephone (212) 460-5133



June 17, 1975

Re Indian Point Unit No. 2
Docket No. 50-247

Mr. Karl Goller
Assistant Director for
Operating Reactors
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Dear Mr. Goller

In accordance with the requirements of the Directorate of Licensing Letter of November 8, 1973, Con Edison herewith submits the results of inspection of hydraulic snubbers installed in Indian Point Unit No. 2. Results are presented for inspections performed during the period of May 5, 1975 through June 3, 1975.

Very truly yours

A handwritten signature in cursive script that reads "Carl L. Newman".

Carl L. Newman
Vice President

mrb

Copy to Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region I
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Penn. 19406

8111070007 750617
PDR ADOCK 05000247
Q PDR

6654

Results of Inspection of Hydraulic Snubbers
Installed at Indian Point Unit No. 2
June 3, 1975

Received w/ Ltr Dated **6-17-75**

Bergen-Paterson Snubbers:

1. Located Inside Containment: Inspection not required
2. Located in PAB and Conventional Plant.

Date of Inspection: Completed June 3, 1975.

Number of Snubbers Installed: 153

Seal Material: Millable gum - 130
(following
replacement) Ethylene Propylene - 23

No. of Snubbers Inspected: All millable gum.

Results

Twelve snubbers had indications of leakage. One contained insufficient fluid to assure operability.

Corrective Action

Seven snubbers with indications of leakage were replaced with units employing ethylene - propylene seals. All other snubbers with indications of leakage were restored to normal fluid level.

Snubbers Supplied by other Manufacturers (Grinnell):
Inspection not required.