

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819




Regulatory Docket File

October 23, 1975

Re Indian Point Unit No. 2
Docket No. 50-247

Director of Nuclear Reactor Regulation
Attn: Mr. Karl R. Goller
Assistant Director for
Operating Reactors
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Gentlemen

In accordance with the requirements of the Directorate of Licensing letter of November 8, 1973, Con Edison herewith submits the results of inspection of hydraulic snubbers installed in Indian Point Unit No. 2. Results are presented for inspections performed during the period of September 10, 1975 through October 9, 1975.

Very truly yours

A handwritten signature in cursive script, appearing to read "William J. Cahill, Jr.".

William J. Cahill, Jr.
Vice President

mk

Copy to James P. O'Reilly, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Penn. 19406

8111070008 751023
PDR ADCK 05000247
PDR

12405

Results of Inspection of Hydraulic Snubbers
Installed at Indian Point Unit No. 2
October 9, 1975

*See with file
10-23-75*

Bergen-Paterson Snubbers **Regulatory Docket File**

1. Located Inside Containment: Inspection not required
2. Located in PAB and Conventional Plant.

Date of Inspection: Completed October 9, 1975

No. of Snubbers Installed: 153

Seal Material: Millable gum - 88

Ethylene Propylene - 65

No. of Snubbers Inspected: All millable gum

Results:

Three snubbers had indications of leakage. All snubbers were in operable condition.

Corrective Action:

All snubbers with indication of leakage were restored to normal fluid level.

Snubbers Supplied by Other Manufacturers (Grinnell):
Inspection not required.