


William J. Cahill, Jr.  
Vice President

Regulatory Docket File

Consolidated Edison Company of New York, Inc.  
4 Irving Place, New York, N.Y. 10003  
Telephone



December 31, 1975

Re Indian Point Unit No. 2  
Docket No. 50-247

Director of Nuclear Reactor Regulation  
Attn: Mr. Karl R. Goller  
Assistant Director for  
Operating Reactors  
Division of Reactor Licensing  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555



Gentlemen

In accordance with the requirements of the Directorate of Licensing letter of November 8, 1973, Con Edison herewith submits the results of inspections of hydraulic snubbers installed in Indian Point Unit No. 2. The inspections were completed on December 16, 1975.

Very truly yours

William J. Cahill, Jr.  
Vice President

enc.  
mk

Copy to Mr. James P. O'Reilly, Director  
Office of Inspection and Enforcement  
Region 1  
U. S. Nuclear Regulatory Commission  
King of Prussia, Penn. 19406

8111110516 751231  
PDR ADOCK 05000247  
Q PDR

Results of Inspection of Hydraulic Snubbers  
Installed at Indian Point Unit No. 2  
December 16, 1975

---

Regulatory Docket File

Bergen-Paterson Snubbers:

Date of Inspection: Inspections completed December 16, 1975.

Number of snubbers installed: 456

Seal Material: Millable gum - 88  
Ethylene-Propylene - 368

~~12-31-75~~

Number of Snubbers Inspected: All millable gum

Results:

Eight snubbers had indications of significant leakage. All units were in operable condition.

Corrective Action:

All snubbers with indications of leakage were restored to normal fluid level. Where necessary, fittings were tightened.

Snubbers Supplied by Other Manufacturers (Grinnell):

Inspection not required for this report.