


William J. Cahill, Jr.
Vice President

REGULATORY DOCKET FILE COPY

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819



September 23, 1975

Re Indian Point Unit No.2
Docket No. 50-247

Mr. Karl R. Goller
Assistant Director for
Operating Reactors
Division of Reactor Licensing
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Mr. Goller

In accordance with the requirements of the Directorate of Licensing letter of November 8, 1973, Con Edison herewith submits the results of inspection of hydraulic snubbers installed in Indian Point Unit No. 2. Results are presented for inspections performed during the period of August 11, 1975 through September 9, 1975.


Very truly yours

A handwritten signature in cursive script that reads "William J. Cahill, Jr.".

William J. Cahill, Jr.
Vice President

mrh

Copy to Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Penn. 19406



8111110839 750923
PDR ADDCK 05000247
Q PDR

11206

Results of Inspection of Hydraulic Snubbers
Installed at Indian Point Unit No. 2
September 9, 1975

Bergen-Paterson Snubbers:

1. Located Inside Containment: Inspection not required
2. Located in PAB and Conventional Plant.

Date of Inspection: Completed September 9, 1975

No. of Snubbers Installed: 153

Seal Material: Millable gum - 88

Ethylene Propylene - 65

No. of Snubbers Inspected: All millable gum

Results:

Five snubbers had indications of leakage. All snubbers were in operable condition.

Corrective Action:

All snubbers with indications of leakage were restored to normal fluid level.

Snubbers Supplied by Other Manufacturers (Grinnell):
Inspection not required.