


Regulatory Docket File



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003



September 3, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-29

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Abnormal Occurrence No. 4-2-29 is submitted.

The occurrence is the type defined by Technical Specification 1.8.b and relates to finding the refueling water storage tank containing less than 350,000 gallons of water as required by specification 3.3.A.1.a.

Following a filling operation of the refueling water storage tank, it was determined that the amount of water contained in the tank was 3,000 gallons less than required. Filling of the tank had been started while the unit was being removed from service for a scheduled shutdown and was completed when the unit was in the hot shutdown condition.

Our preliminary review of this occurrence indicates that the safety implications are not significant since the amount of water in the tank was above that indicated necessary by the accident analysis.

This abnormal occurrence was identified on August 30, 1974 and reported to Mr. Anthony Fasano of your office on August 31, 1974.

Walter Stein

Walter Stein, Manager
Nuclear Power Generation

cc/ Edson G. Case

8110240504 740903
PDR ADOCK 05000247
S PDR

9341