

Regulatory Docket File




Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003



August 9, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-24

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, we wish to inform you of an Abnormal Occurrence (A.O. 4-2-24), which was identified and reported to Mr. Anthony Fasano of your office on August 9, 1974.

The occurrence is the type defined by Technical Specification 1.8.d. and related to a malfunction of main steam isolation valve No. 21.

The incident occurred following actuation of the safeguards system. Safety injection was initiated shortly after Unit No. 2 tripped on low low steam generator level from approximately 30% power due to the closure of No. 23 main steam isolation valve.

Following the safeguards actuation, No. 21 main steam isolation valve failed to close. The failure was determined to be due to a packing gland follower which was cocked. After realignment of the follower, the valve was tested several times and closed successfully.

A follow up report on this occurrence will be submitted within ten days.

Walter Stein

cc/ Edson G. Case

8442

8110240554 740809
PDR ADOCK 05000247
S PDR