


Regulatory Docket File




Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003



August 9, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-23

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406



Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, we wish to inform you of an Abnormal Occurrence (A.O. 4-2-23), which was identified and reported to Mr. Anthony Fasano of your office on August 8, 1974.

The occurrence is the type defined by Technical Specification 1.8.d. and related to a malfunction of No. 21 Emergency Diesel Generator.

The incident occurred following actuation of the safeguards system. Safety injection on low pressurizer level coincident with low pressure was initiated shortly after Unit No. 2 tripped on overtemperature delta T from approximately 98% power.

Following the safety injection actuation, No. 21 emergency diesel generator failed to start. Investigation revealed that the diesel had tripped on "overcrank". The diesel was manually started successfully following the occurrence.

Our investigation into the incident is continuing and a follow up report on this occurrence will be submitted within ten days.

Walter Stein

cc/ Edson G. Case

8110240558 740809
PDR ADCK 05000247
S PDR

8500