



ATTACHMENT I

Docket No. 50-247

Consolidated Edison Co. of N.Y., Inc.

LER-78-006/01T-0

Indian Point Unit No. 2

On February 13, 1978, while in the process of going from hot shutdown to the cold shutdown condition in preparation for the present refueling outage, a pinhole leak was discovered at a socket weld joint for a vent connection on the No. 23 reactor coolant pump seal injection supply line. This event is of the type described in Technical Specification 6.9.1.7.1(c).

Since a cold shutdown and subsequent drain down was in progress, this leak had no effect on plant operation. Repairs to the socket weld joint are planned for the outage presently in progress.

A similar event was reported on February 23, 1977, as Reportable Occurrence R.O.-77-2-2(B) for Unit No. 2, Docket No. 50-247.