

LICENSEE EVENT REPORT

TEIR-77-2-7

(PLEASE PRINT ALL REQUIRED INFORMATION)

CONTROL BLOCK: 1 2 3 4 5 6

LICENSEE NAME: 01 N Y I P S 2 14
 LICENSE NUMBER: 00-000000-00 25
 LICENSE TYPE: 4 1 1 1 1 30
 EVENT TYPE: 9 9 31 32

REPORT TYPE: 01 CONT 57 58
 REPORT SOURCE: 01 60
 DOCKET NUMBER: 050-0247 68
 EVENT DATE: 082977 74
 REPORT DATE: 092977 80

EVENT DESCRIPTION

02 During normal operation, a routine inspection revealed a leak in a feed-
 03 water system seismic restraint (3CDSR13). Although the restraint was
 04 still operable, a decision was made to remove and replace it before it
 05 became inoperable. A new restraint was installed within the time limits
 06 permitted by Tech. Specs. [TEIR-77-2-7]

SYSTEM CODE: 07 C H 10
 CAUSE CODE: E 11
 COMPONENT CODE: H A N G E R 12 17
 PRIME COMPONENT SUPPLIER: N 43
 COMPONENT MANUFACTURER: B 2 1 1 0 47
 VIOLATION: N 48

CAUSE DESCRIPTION

08 A Bergen Patterson Seismic Restraint, Model HSSA-3, developed an oil
 09 leak at its seal, and was replaced to preclude further deterioration.
 10

FACILITY STATUS: 11 E 9
 % POWER: 1 0 0 10 12 13
 OTHER STATUS: NA 13
 METHOD OF DISCOVERY: A 44 45
 DISCOVERY DESCRIPTION: Restraint Inspection 46 80
 FORM OF ACTIVITY RELEASED: Z 9
 CONTENT OF RELEASE: Z 10 11
 AMOUNT OF ACTIVITY: NA 44 45
 LOCATION OF RELEASE: NA 46 80

PERSONNEL EXPOSURES

13 NUMBER: 0 0 0 11
 TYPE: Z 12
 DESCRIPTION: NA 13 80

PERSONNEL INJURIES

14 NUMBER: 0 0 0 11
 DESCRIPTION: NA 12 80

PROBABLE CONSEQUENCES

15 NA 80

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 9
 DESCRIPTION: NA 10 80

PUBLICITY

17 NA 80

ADDITIONAL FACTORS

18 NA 80

19 8111040003 770929
 PDR ADOCK 05000247
 S PDR

NAME: John M. Makepeace

PHONE: 914-739-8823