



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

May 16, 1977

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406


Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Reportable Occurrence No. 77-2-11(A), confirms a telephone report to Mr. John Streeter of your office, this date.

The occurrence is the type defined in Regulatory Guide 1.16, Revision 4, Section C.2.a.(2).

On May 16, 1977, while operating at 100% reactor power, it was determined that the contents of the refueling water storage tank were approximately 5,300 gallons below the minimum Technical Specification of 350,000 gallons. Sufficient water was added to the tank to bring the contents above the required amount.

Very truly yours,


Edward F. Kessig,
Acting Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Director, Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20535

8111040457 770527
PDR ADDCK 05000247
S PDR