



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

March 10, 1977

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following confirms the telephone notification of Mr. John Streeter of your office on March 9, 1977 of Reportable Occurrence No. 77-2-4(A). The occurrence is the type defined by Regulatory Guide 1.16, Revision 4, Section C.2.a(2).

On March 9, 1977, while operating at approximately 100% of rated power, it was recognized that a shock suppressor (snubber) which had been identified during the November, 1976 steam generator inspection outage as needing corrective action, had not been repaired. This particular snubber (3CD SR-13) is located on the 3" recirculation return line from No. 23 motor driven auxiliary boiler feedwater pump. Repairs to the snubber were immediately initiated and it is expected that it will be returned to an operable condition within the time limit permitted by the Technical Specifications.

Very truly yours,

FoR

Edward F. Kessig,
Acting Manager
Nuclear Power Generation
Department
Indian Point Station
Buchanan, New York 1051

8111040503 770310
PDR ADOCK 05000247
S PDR

Copy to: Director of Nuclear Reactor Regulation
Attn: Mr. William F. McDonald, Director (2 copies)
Office of Management Information and
Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555