


William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819



December 23, 1976

Re: Indian Point Unit No. 2
Docket No. 50-247
R.O. -76-2-24(A)

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa 19406



40

Dear Mr. O'Reilly:

We transmit herewith Reportable Occurrence report R.O.
-76-2-24(A). Three copies of this letter and the attach-
ment are enclosed as required.

Very truly yours,

William J. Cahill, Jr.
Vice President

attach.

Copy to: Director of Nuclear Reactor Regulation
ATTN: Dr. Ernst Volgenau, Director (40 copies)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director of Nuclear Reactor Regulation
ATTN: Mr. William G. McDonald, Director (3 copies)
Office of Management Information and
Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

13116

8111040628 761223
PDR ADOCK 05000247
S PDR

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

[PLEASE PRINT ALL REQUIRED INFORMATION]

L	I	C	E	E	S	E	L	N	U	M	B	E	L	I	C	E	T	T						
01	N	Y	I	P	S	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15						25	26				30	31	32				

C	A	T	E	G	O	R	T	T	S	O	U	R	C	E	D	A	T	E	R	E	P	O	R	T	D	A	T	
01	CON	T					T																					
7	8		57	58	59	60	61					68	69															80

EVENT DESCRIPTION

02 | During power escalation following a unit outage, reactor power was raised
 03 | to 68% although the indicated axial flux difference had been outside
 04 | its target band for a period in excess of the requirements of Tech.
 05 | Spec. 3.10.2.7.2. The operator, on realizing this condition, imme-
 06 | diately reduced power to below 50%, and held it there until the require-

S	Y	S	T	E	M	C	O	D	E	S	C	O	D	E	S	C	O	D	E	S	C	O	D	E	S	C	O	D	E
07	Z	Z	A	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z	Z
7	8	9	10	11	12					17	43																		80

CAUSE DESCRIPTION

08 | The cause of this event was a misinterpretation of the requirements of
 09 | Tech. Spec. 3.10.2.7.2 by the operator. Operators have been rein-
 10 | structured on the applicable requirements of Tech. Specs. in this regard.

F	A	C	I	L	I	T	S	T	A	T	O	T	H	E	R	S	T	A	T	O	F	D	I	S	C	O	V	E	R	D	E	S	C	O	N
11	0																																		
7	8	9	10	11	12	13																								80					

F	O	R	M	O	F	A	C	T	O	F	R	E	L	O	C	A	T	I	O	N	O	F	R	E	L	O	C	O	N
12	Z																												
7	8	9	10	11																									80

PERSONNEL EXPOSURES

N	U	M	B	E	R	T	Y	D	E	S	C	I	O	N
13	0	0	0	Z										
7	8	9	11	12	13									

PERSONNEL INJURIES

N	U	M	B	E	R	T	Y	D	E	S	C	I	O	N
14	0	0	0											
7	8	9	11	12										

PROBABLE CONSEQUENCES

15 | NA

LOSS OR DAMAGE TO FACILITY

T	Y	P	E	D	E	S	C	I	O	N
16	Z									
7	8	9	10							

PUBLICITY

17 | NA

ADDITIONAL FACTORS

18 | (Event Desc. Cont.) - ments of Tech. Spec. 3.10.2.7.2 were satisfied.

19 | (R.O. 76-2-24(A))

NAME: Austin J. Decker II

PHONE: 914-739-8823