

Peter Zarakas
Vice President

REGULATORY DOCKET FILE COPY

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N.Y. 10003
Telephone (212) 460-5133

Rec'd
8/24

August 18, 1978


Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Penn. 19406

Dear Mr. Grier:

In accordance with Technical Specification 6.9.2.c, a visual fuel inspection was conducted at Indian Point Unit No. 2 during the unit's second refueling outage. No clad flattening was observed. In addition, no evidence of fuel cladding failure or any other condition that could lead to unacceptable fuel performance was observed. A report of the visual fuel inspection program and results is provided as an attachment to this letter.

Very truly yours,


Peter Zarakas
Vice President

attach. **SEE REPORTS**

cc: Director of Nuclear Reactor Regulation
ATTN: Mr. A Schwencer, Chief
Operating Reactors Branch #1
Division of Operating Reactors
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

782360111

8110290052 780818
PDR ADDCK 05000247
PDR

3
A001
5/19
R2000
20
CYS