

William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

March 10, 1978

Indian Point Station
Unit No. 2
Docket No. 50-247

Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier

Section 4.14.D.1.a of the Unit No. 2 Technical Specifications defines the surveillance requirements for the smoke detectors listed in Table 3.13-1. In the process of developing the prerequisite surveillance procedures for these particular detectors, it was found that those detectors in the areas of the boric acid transfer and containment spray pumps were not installed as was originally indicated in Con Edison's revised Fire Protection Program which was submitted to the Commission in April, 1977. A review of this situation indicates that, although shown on the applicable drawing, these detectors were intended for installation during the on-going refueling outage. All material for the installation is either on hand or has been ordered and we expect that the installation will be completed before startup for the next cycle.

Very truly yours



8110300020 780404
ADOCK 05000247