



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

November 10, 1976

Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, the following report of Reportable Occurrence No. 76-2-22(A) confirms a telephone report to Mr. John Streeter of your office, this date.

The occurrence is the type defined in Regulatory Guide 1.16, Revision 4, Section C.2.a(4).

On November 9, 1976, while in the cold shutdown condition, the secondary side of No. 24 steam generator was being drained in preparation for maintenance work. Due to a tube leak in this steam generator, a portion of the unborated secondary fluid entered the reactor coolant system causing an unplanned reduction in boron concentration. The minimum shutdown margin, required by the Technical Specifications, was not compromised by this occurrence.

Very truly yours,

Edward F. Kessig,
Acting Manager
Nuclear Power Generation
Indian Point Station
Buchanan, New York 10511

Copy to: Director, Office of Management Information
and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8111070226 761110
PDR ADDCK 05000247
S PDR