


DR Central Files



Consolidated Edison Company of New York, Inc
4 Irving Place, New York, NY 10003

October 25, 1974

Re: Indian Point Unit No. 2
AEC Docket No. 50-247
A.O. 4-2-34

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region 1
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly:

In accordance with the Technical Specifications of Facility Operating License No. DPR-26, we wish to inform you of an Abnormal Occurrence (A.O. 4-2-34), which was identified and reported to Mr. Bert Davis of your office on October 25, 1974.

The occurrence is the type defined by Technical Specification 1.8.d and relates to a malfunction of No. 22 Diesel Generator.

During the conduct of periodic surveillance test PT-M21, it was found that the generator output breaker for No. 22 diesel generator would not close. Preliminary investigation into the cause of the occurrence led to the determination that an auxiliary relay of the generator voltage output relay failed to operate due to a loose wire.

Immediate action following this occurrence consisted of verifying the operability of No. 21 and No. 23 diesel generators which consisted of starting them and synchronizing them to their respective 480 volt buses. Both diesels operated successfully.

Following identification of the cause, the wire was tightened and the diesel tested satisfactorily.

A.O. 2

A follow up report on this occurrence will be submitted in ten days.

8111070343 741025
PDR ADOCK 05000247
PDR

CC: Mr. Leon G. Cove *Walter Allen*